

PDP-6

HARDWARE LOG

JUL 66 - 6 APR 67



53-110
EYE-EASE PAPER
Made in U.S.A.

SIGN AND DATE

ALL ENTRIES

ARR

5 Jul 66

Hardware log started

SPR

5-July 66 Parity error

MA 120533

Mem box 3

MA 001533

Rel 120

Data 540140002573

Bug discovered:

The computer appears to be missing one very important part:

The log. The system ~~log~~ died (~~that~~ due to a downward-sloping power switch) & the hardware for recording this event was not present.

POWER ON 7-6-66 LYONS 0900 814.0
RAN MARGINAL CHECKS ON CORE 243 + PARITY
OPTION (169) OFF AT 12:07

1400 6 JUL 66 HRS = 819.8

PARITY ERROR:

PMA = 031045

PMB = 00134 — 6

CORE 1 selected

DATA in PMB = Data in CMB

PAR ODD + PARITY BOTH OFF

ERROR REALLY IN MEMORY

WITH EX amine & deposit

PUTTING DATA BACK IN WORKED

PARITY & PARITY ODD WERE BOTH ON:

APPARENTLY THE DATA WAS IN MEMORY
INCORRECTLY

SR Russell

7-6-66 1400

TTY 1 ~~Does~~ DOES NOT ECHO BACK. J.L.

JOBSY NON EX-MEM

•R DDT

DDT=140

200/ TLNE JOBUUO JRST 200

200G+C

•R UN\INS4

ERROR IN JOB 2

NON EX MEM AT EXEC 3613; UO AT USER 3164
+C

Wühr

7-6-66

7-7-66 POWER ON 9:05 829.5 LYONS

BIT 5 OF IOB ON ALL THE TIME. FOUND
SHORTED TO CABLE AT 1A1 END OF IO CABLE
BETWEEN THE 136 AND 630.

TTY1 TROUBLE WAS FIXED BY REPLACING 470
1K11 IN THE 630 OFF AT 11:30 J.L.
ALSO RAN BLT FOR 1 HOUR.

7-8-66 POWER ON AT 8:45 848.8 J.L.

RAN BLT TIL 10:30 WHILE IOB WAS
BEING WIRED. MONITOR ON AT 10:30

7-8-66 THE 4706 MODULE FOR 1K11 IN THE 630
HAS BEEN REPAIRED & REPLACED. J.L.

Power down 7:17 PM 7-8
859, 2 Sauter

POWER UP 1450 9 JUNE

D. Pool

TTY 1 cannot send characters.
The teletype is OK - problem appears to
be in the scanner.

7-9-66 6:15 PM

John Sauter

Parity ERROR

MA = 133137 (box 3)

MB = 436000007205 ©

CP MA = 7137

Parity ERROR

MA = 133137 (box 3)

MB = 436000007205 ©

CP MA = 7137

In both of the above cases Job 1
(cty) had just started running
MIDAS.

8:05 PM 7-9-66

John Sauter

Power OFF 8:15 PM 7-9-66

J. Sauter

Memory parity - same as above.

21:42

CP temp = 76°

J. Sauter

System died. Non-ex mem @ 5514
22:23 7/9

John Sauter

7/10 11:30 PM.
Tried to start system. Failed

John Mc Carthy

7/10 14:15 found DEC dump in reader
backwards. Labeled system OK
Weber

7/10 15:08 Parity error

reloc 0 MA 2

PM A 100000 FNC SEL ON ??

Data 546360000002

all gone system

Weiher

MISS:

BEGIN Parity ERROR

CP temp

MA = 133137 (box 3)

= 93° !

MB = 436000007205

⊙

CPMA = 7137 END

7:20 PM

7-10-66

7:25 PM 7-10-66

same thing same place same data
same program (midax!)

7:27 same. This is getting frustrating.

check after syst reset loc ad 476000007205 ⊕

11:50 PM 7-10-66

Another exciting party error

MA = 107511

MB = 366300007505

⊙

Box 3

CPMA 7513

Also MA = 104245

MB = 442000000665

⊙

CPMA = 4247

Box 3

temp = 60

4:47 AM 7-11-66 Power off

CP temp = 76° J. Sauter

7-11-66 POWER ON 8:45 AM

892.6 V.A.

TTY 1 OK now - J.L.

The usual party error - MA = 133137 MB = 436000007205
CPMA 7137 Party light on

19:38

on/under

put on Box 3 on maint. by agent

now no error? to reproduce the condition, load
MIPAS into the top 22k of memory
and let it assemble TEKO. J.S.

DTA1 is doing a lot of swinging for each
record. DTA2 is ok.

5:30 AM 7-12-66 J. Sauter

6:20 AM 7-12-66 913.65 hrs

Power OFF

CP Temp = 78°

no trouble with memory since we put Box 3
in manual. It is still there.

John Sauter

7:50 AM 7-12-66 913.7 J.A.

P. ON

Replaced Sense Amp For BIT 3 IN CORE 3 J.L.

ADJUSTED DTA 2 TRANSPORT STOP TIME. HAD MACHINE
FOR 1.5 HRS.

Power off 4:40 7-13-66 on J.W.

CONTIN

AS THE DATASET I/O LEVELS AND PULSES ARE BIPOLAR
EXAMP:

ON OR A "ONE" STATE IS $+5 \rightarrow 25$ VDC

OFF OR "ZERO" STATE IS $-5 \rightarrow 25$ VDC

I MADE A ~~CHIC~~ DIVIDER FROM PLUS 10VDC OF THE 630
THRU A GROUP OF SWITCHES I ADDED BELOW THE
PATCH PANEL AND SENT THIS TO THE DTR TERM. OF
ALL DATASETS TO TURN THEM ON AT WILL.

RANDY

1-14-66 PAINTER ON 9:00 850.7 J. Lyons

RAW T/S MAINS 10 MIN.

RAW SET 10 MIN.

TOOK MARGINS ON 136 LECTURES

CHECKED DELAYS ON 136 LECTURES

25 MS, DELAY WAS 45 MS. RESET TO 35 MS.

225 MS, DELAY WAS 230 MS. RESET TO 184 MS.

300 MS, DELAY WAS 345 MS. RESET TO 201 MS.

* THIS DELAY SHOULD BE SET TO APPROX. 180 MS.

RELEASED MACHINE TO USERS AT 10:30 AM.

POWERON 7-15-66 - 967.9 JA.

CONS INST. FAILS INTERMITTANTLY. (CONS T 3)
OUTPUT OF PA (INSY) TO AMPLITUDE (LESS THAN 2V)
INPUT TO PIN X RINGS AND IS TOO NARROW.

EXAMINE WHILE RUNNING CAUSES STALL CONDITION
IN KEY CYCLE IF THE ADDRESS BEING EXAMINED
HAS BIT 25 OR HIGHER BIT. (WRITE IN USER MODE)

Parity error

MA 117127

Data 305040002657

parity on
box 3 cpma

5127

Weber

PARITY ERROR

MA = 031125 (Box 1)

MB = 256003000000 Parity = 1

CPMA = 001125

RELOC = 030 (user mode)

7-15-66 0210

The '35 (ctr) is out of paper. We have been using the back of an old listing for some time, but now even that is gone.

J. Sauter

7-16-66 9:00 POWER ON 989.16
~~POWER OFF~~ -JA

CONS 1,15 INSTRUCTION LOOSES AGAIN!!

LH(MB) = 002671

LH AR = 002672

LH(MR) = 011446

CONS CNT
RH = 0 ⇒ TRAP
THE SOB.

INSTR = 257

AC = 1

IR = 15

MCM = 2 3 2057

AC 15 = LH(002671)

AC 1 = 11446

AC 2 = 0

POWER 10:05

Parity MA 54652

Date 05770712665C

Parity bit on temp 80

box 0 15:37 7-16-66

repeated parity errors in box 0 all different locations

zeroed core box 0 still gives parity error

Bit 25 always on on read

5:10 PM 7-16-66

The system seems very sick.

We will try the diagnostics

BLIT TEST will not READ IN!

John Sauter

8:35 PM 7-16-66 Power ON

Non-ex MEM trying to type date into system. Ran with Disable Memory

MA = 020754

PC = same

CP TEMP = 76°

BLIT wont read in.

Power OFF

7-16-66 9.30 PM

I HAVE BEEN LOOKING AT THE SIC SIX AND TRYING TO SEE WHAT IS WRONG FIRST:

I GOT A PARITY ERROR BUT IT WAS NOT BAD PARITY

I LOADED JRST.+1 IN TO LOC 20 THIS IS CORE 0 LOC 0. THE CORE BOX WROTE 254000000021 WHICH IS WHAT I PUT THERE, CORE FINISHED THE WRITE CYCLE AND WHEN IT WAS DONE THE PARITY BOX SAID THE FOLLOWING

PARITY BIT WAS AS ONE (THAT SEEMED RIGHT FOR THEIR WAS ONLY 6 BITS TO THE WORD BUT IT ALSO COMPLAINED OF BAD PARITY. THIS SEEMS ODD BECAUSE THE CMB = PMB, AND THEY WERE RIGHT

FURTHERMORE UPON DOING AN EXAMINE OF LOC 20 IT VERIFIED THAT CORE 0 LOC 0 (MAS=20) CONTAINED 254-----21 WHY?
BAD PARITY

THE SECOND READOUT OF THE SAME LOC SHOWED THE PARITY BIT WAS NEEDED AND IT WAS GOOD (NO ERROR) THE THIRD TIME OF SAME GAVE ERROR

BUT THE CONTENTS OF THE ABOVE CELL HAD NOT CHANGED ----- RANBY

7-17-66 -- Ø23Ø

RE: PREVIOUS NOTES.

Observed that bug goes away when 163 #1 (core Ø) is in P2 mode, come back when core in MULTI.

THEOREM: Core Ø forgets pulses when in MULTI mode, probably in the $CMC AW RQ \leftarrow Ø \Rightarrow [10000 DLY]$

$\Rightarrow CMC RQ SYNC \leftarrow 1$ circuit.

Proof: Exchange relevant modules between core Ø and core 1; namely, 1E21, 1D18, ~~1H22~~, 1D2Ø; no great effect.

REVISION OF THM: $CMC AW RQ \leftarrow Ø$ is not being generated sometimes. We have no draws of this logic, as it involves the memory hold mod.

DAMN R. CLEMENTS!!
Draws should come with machines.

D.P.

7-17-66

0643

1003.5 HR.

Power off. - D.P.

2:35 PM 7-17-66

Power ON Ran Dec tape test.

on DTA7 (exdata)

All memories in P2 and Run.

CP TEMP = 70°

no complaints for DTA7.

Ran on DTA5. Runs Ok.

Loaded Monitor (3:10 PM)

System died 5:40 PM 7-17-66

PC change was enabled (?)

error flag was up in the parity box
and the stop switch was on but the
machine was still doing something.

PI 2 in progress (and 7).

J. Sauter

System died 6:15 PM 7-17-66

Non Ex Mem, CPA ill op.

PI 2 in progress
monitor will not restart at 140

System died 7:02 PM 7-17-66

PC CHNG ENABLED

AROV ENABLED

PI 2 active (+7)

7-17-66 ~~1915~~ 1915

PC CHG ENB and AROF ENB come on mysteriously, causing system disast.

D.P.

7:58 PM 7-17-66 Power OFF

CP TEMP = 75°

2052 -- PWR ON, 1008.9 HRS

D.P.

10160

4:AM 7-18

Parity error

CP MA = 40172

PB MA = 172170

9:00 AM J. E. TRAN TSMAN. & BETOK
TRIED USING ALL MEM. IN MULTI. TRAN OK.

USED A DEVICE TIL 10:00

7-19 6:15 A.M.

ERROR IN JOB 2
NON EX MEM AT EXEC 13772; UO AT USER 672
↑C

-
-
-
-

*R EDITOR

↑C

.R EDITOR

*S5,PROG2

*P1015

01015 PT20 (CSETQ NUM(PLUS 1 NUM))

*I1020,5

01020 (SETQ(\ VOR(INTERN(MAKNAM(CONS

ERROR IN JOB 2

NON EX MEM AT EXEC 13772; UO AT USER 672

↑C

.SYSTEM RELOADER AT THIS TIME.....

↑C

.R EDITOR

JOB 1 INITIALIZED

MONITOR IS RCC 2.4M

19-JUL-66

620:49.27

*S5,PROG2

*P1015

01015 PT20 (CSETQ NUM(PLUS 1 NUM))

*I1020,5

things ran fine past here ↓

~~Everything ran O.K. after I reloaded the system.~~

Everything ran O.K. after I reloaded the system.

9:00 AM

7-19

Power off

meter = 1043.4

7-19 POWER ON (J.L.)

9:15

1043.4

Removed 150-ohm TERMINATING RESISTOR ON
1H2Y TO DECREASE LOADING ON CONST3 PA.
CONS TEST WAS FAILING DUE TO 10 AMPITUDE
PULSE (2.5V) OF CONST3. THE FUNCTION OF THIS
SIG. IS TO SET THE TRAP FLAG AND INITIATE ST'S.

THE OVERTSHOT NOW PRESENT CAUSES NO PROBLEMS.

SYSTEM OUT OF INTERLEAVE FOR D. POOLE - J.L.

7-20-66

0125

POWER OFF P.P.

7-20-66

0330

Power on P.P.

7-20-66

0940

Power off

7-20-66

0915

POWER ON J.L.

1064.8

INSTALLED 1664 (NO INTERLEAVE) MODULES FOR 167
(IN PO SLOTS)

INTERCHANGED 4706 MODULES FOR TTY 0 & TTY 1

TTY 0 & 1 BOTH OK NOW.

RAN HI SPEED MEM. CHK RBD FOR 20 MIN. (OK)

RAN BLT FOR 1/2 HR. (NO BURPS!)

Returned Machine To users AT 10:40

7-21-66 0900 Power on J. Lyons 1078.8

PARITY ERRORS (CORE 1) DROPPING BIT 33. Replaced
Sense Amp. OK NOW

~~THE~~ THE ADDRESS LINES AND ~~DATA~~ DATA LINES (Mem Bus)
IS NOW WORKING FROM 167 TO CORE 3, 2 & 1.

FOUND 2 1665 Modules HAD BAD SOLDER CONNECTIONS
FROM THE REAR SOCKET TO PC WIRING. BOTH CARDS
ARE NOW REPAIRED.

7-22-66 0910 Power on J.L. 1095.4

~~7-23-66 1552 Power on D.P.~~

7-23-66 1552 Power on D.P.

7-23-66 1558 Persistent

parity error - loc. 46400.

7-24-66 0130 VIDEO WORKS!

POWER OFF.

SAR

7-24-66 10:00

~~5000 5072 1000 54~~

CORE 1 SOLID PARITY ERRORS !!

RUNS FIND IN OTHER CORE BOXES

~~YOU CAN GET THIS~~


POWER OFF 12:15

1440 24 JUL 66 POWER ON

INVESTIGATED DATA-SET TROUBLES.

FOUND RECEIVER BOARD FOR UNIT 1
BAD REPLACED 4706 AT 630 1K12

NOTE BAY NUMBERING ON 630 BAY 0



BAY 0 BAY 1

NOTE THE LEFTMOST IS BAY 0
(PRONOUNCED BAY (BLANK) IF NECESSARY)

WE NOW HAVE YET ANOTHER NUMBERING SYSTEM:
IT ~~STARTS WITH~~ GOES

(BLANK), 1, 2, ...

ANYWAY OTHER THAN BAD 4706 TTY'S
SEEM TO WORK and external TTY'S seems
to work

SRR

1720 24 JUL 66

LINE PATCH 1 appears to drop bits
randomly so it is disconnected right now
TWX and TWX' lines work all right
1776 was in use for about 1 hr with no
trouble

SRR

7-25-66 POWER ON 1133.6 J.L.

PARITY ERRORS IN CORE 1. WE ARE DROPPING
THE RITE HALF OF WORD. AFTER MACHINE WARMED UP
CORE 1 IS OK. LOOKS LIKE COLD PROBLEM. WILL
LOOK TOMORROW.

0110 20 Jan 66

AIR CONDITIONING JUST STARTED
DUMPING ~~A~~ WARM (NOT COOL, BUT WARM)
AIR INTO COMPUTER ROOM. CHECK
THE HAYWIRE ON THE DAMPERS
IN BACK. TEMP = 89°

JRR

7-26-66 PWR ON. Temp 80° 1148.7 J.L.

CORE 1 DROPPING HALF WORDS (EITHER HALF)
AT RANDOM ADDRESSES.
AFTER Module Change THIS TROUBLE WENT AWAY.
See Note. Picked up BIT 21 WHEN THE LEFT HALF
OF WORD WAS OK'S. Replaced ~~same~~ INHIBIT DRIVER
FOR THIS BIT. OK NOW.

RAM MATRONS ON ALL 4 MAIN CAR.

ALL ORIG. Modules BACK IN THEIR ORIG. LOCATIONS.

28 Jul 66

Printer ~~turns off~~ ~~Start~~ and
Printer hangs up ~~printing~~
Pushing stop turns on both stop and ~~start~~
and the printer hangs up. only Restart on
the end will un ~~hang it~~.

7-27-

POWER ON 9:00

1172.1 J.L.

RAN BLT FOR 1 HR 40 MIN. OK!

INSTALLED PRINTER & LOGIC - RAN DIAGNOSTIC OK!
(IT LIVES!)

the following differences exist between TTY and LPT

TTY
 single quote
 ↑
 @
 ←

LPT
 right quote
 circumflex
 tilde
 left quote
 underline

7-27 2330

ADJUSTED TRACTOR INDEX ON UPPER AND LOWER UNITS
THEY NOW TRACK PROPERLY AND YOU CAN GET PROPER
WEB TENSION & FORM TENSION RUN TIME 171.1

P.O. BILL W. MADE UP
NEW VERTICAL FORMAT TAPE

RANDY

7-28-66 Power Still on.

1194.3

Replaced ALL CABINET FILTERS.

Should

7-29 INVESTIGATED NON-EXIST MEM PROB. - W/IDEN
CORE 0 IS IN MULTI. BLT REVEALS THIS
PROBLEM NICELY. INTER-CHANGED I/O MODULES
TO MAKE CORE 0 BE ADDRESS'D AS CORE 1 &
VICE VERSA. TROUBLE STILL STAYS IN AREA. CORES
CABINET. IT NOW STOPS ON NON-EXIST MEM WITH
P2 ACTIVE ON. WILL LOOK REPAIR MONDAY.

29 Jul 66 2000

Printer hangs up.

Pushing STOP and START turns on both STOP

Only Reset on the end will clear it

~~This Hang up is similar to~~

the reset makes the machine go again, but a character is lost.

It usually happens at the same place in a file.

SPR

4

2100

System Reloaded & Power off
~~still~~ bug went away.
tired system.

MI bit 9 appears to have a
~~bad~~ bad light driver.

8-1-66 PANOR ON 1279.8

THE 6113'S (1424) WERE EXCHANGED BETWEEN
CORE 0 & CORE 1. ALL 4 CORES NOW RUN
IN MULTI MODE.

8-1-66 LPT. IS BAD (LOW SPEED DRIVE CLUTCH
BELT BROKE) IT IS BADLY FRAID AND SPLIT
1000AM IT IS THE BELT THAT DRIVE THE PAPER
FEED (THE CLUTCH IS THAT BIG BRASS
FLY WHEEL ON THE LEFT SIDE

RANDY

8-1-66 2230

Core 0 died mysteriously---

MA, RB, WR, INVH = 0 (RUN mode), RS = 1.

Repeated twice. Placed in P2

briefly; didn't happen. Placed in

MULTI, MAINT; didn't happen
D. Poole

Part error

Box 3 MA 76400

Data 260700000000

CPU MA 400

continuous pair errors box 1

RNA 40000

Data 710600000000

bores on p2 does not stop

CPU MA 40000

box 1 loses lower 1/2 word

bit 22 - 28 and 30-31 if any on and
bit 21 on 1/2 word goes away

top 70 ~~bores on p2 does not stop~~

M. Weiber
J. Allen

8-2-66 Power on.

1294.9

8-2-66 1205

Memory stop doesn't work
APP

8-3-66

5:00

1319.3

1319.3

Replaced IM15A W126. Pin K not
going up to GND. To (1) + MC STOP.
RAN MARGINS IN CORE 0 (on MULTI) TO FIND
MULTI PROBLEM. FOUND GIVE L ON 61D IN
1424 KENRAD OUT AT +12 ON B LINE. Replaced

8-2-66

12 05

MEW Timing

Core 0

0.55


11

RQ RS-3

RQ0

-3

ADRS ACK0
-3



core in Run

~~in core~~

~~AW Rec.~~

~~ER pin 1666~~

AW Rec
1666
pin ER

core in multi

RQ → ADRS AC = 550ns


RQ → RQ RS = 1.1 μs

RQ → AW Req = 1.8 μs

(redy for next cycle)

} all are 200ns longer in MAINT

1 1 1 1 1
6 1.7 1.8 1.9 2.0 μ S



8-3-66

J.L.

1324.2

PARITY ERROR CORE 1 LOC. 075040

PARITY BIT OFF, CONTENTS = 326300003040

8-4-66 LRR

POWER OFF - 0335

8-4-66 J.L. PWR ON.

1336.0

ADDRESS STOP DID NOT WORK AGAIN!

TRACED TROUBLE TO INTERMITTANT Delay Module

(1316) IN 1M16. Replaced Module. OK AGAIN! (?)

8-4-66 1815 parity error

loc 140000 core 4

contents 0

8/5/66 WMW

POWER ON

1352.9

8-5

J.L.

PWR ON

1354.0

TEMP 60°

CORE 0 WAS HANGING UP WITH AN RD OFF, ADDR, DATA AND SYNC IN. + ADDRESS ERRORS ENDING WITH THE TROUBLE LEFT AS CORE WARM UP TO 65°

CORE 1 WAS DROPPING HALF WORDS (R. 0.5). AREA 1 FOUND

1 K 5 SEEMS SENSITIVE TO MAKING THIS TROUBLE HAPPEN. LATER ON I COULD NOT MAKE TROUBLE TO COME BACK AGAIN BY TESTING EXHIBIT 02 IN THIS AREA. (OR TAPPING)

8-6-66

The CTY will occasionally drop a character (doesn't even print a null in its place)

John Sauter

Map of interleave switches:

There are eleven (11) switches, located as follows

- 1) CP ~~rack~~ ^{BAY} 2 level L (front)
- 2) FAST MEMORY top front
- 3) CORE BOX 0 ~~Box~~ ^{BAY} 1 level E left front
- 4) " " 1 " " " "
- 5) " " 2 " " " "
- 6) " " 3 " " " "
- 7) CORE BOX 0 ^{rear} BAY 1 Behind the 1035's
- 8) CORE BOX 1 ^{rear} BAY 1 Behind the 1031's
- 9) " " 2 " " " "
- 10) " " 3 " " " "
- 11) 1.67 data channel level B front

caution: the switches in the rear of the core boxes are unlabeled.

now in interleave

1500 2 AUG 66

DTA 1 L Hub SCRAPES ON MOUNTING PLATE

SRP

Moved Hub out a hair - work OK

SRP

1800 6 Aug 66

TJ4 3 doesn't work
locked keyboard

OK
NOW!
J.L.

6 Aug 66 1830

DTA 6 out of adjustment ~~top~~
Lens slack in tape

Bill Oberker

0230 ? Aug 66

~~The~~ the monitor behaved strangely.

Ran dectape test. It complained

about tape 60 a scratch type. Different complaints on different drives. ~~The~~ Mostly error 3. Rewriting timing and mark and blockmarks made the trouble almost go away.

I suspect that both that tape and the dectape logic are marginal

and together they cause trouble,
or else that there is a temperature problem.
It got noticeably warmer as the tests
progressed.

SRR

0236 7 Aug 66

Power off SRR

0955 7 Aug 66

Power on J. Sauter

1750 7 Aug 66

Power off SRR

0912 8th Aug 66

1408.0

Power on R. Doren

1810 9 Aug 66

LINE PATCH Φ (TTY 1)

does not receive teletype characters
very well. it drops them.

SRR.

0900

9th Aug 66

01426.4

Power On

R Duran

J.L. Replaced BURNT PWR LINE WIRE IN 166

RAN PT 1-2-4-5A ^(75 MIN) INST TEST. 15 MIN. (OK)

RAN BLT 15 MIN (OK)

RAN DECTAPE TEST UNIT 6 (EXDATA & DCTEST) (OK)

RAN Mem CHKTRBD (OK)

System up 10:30

8-9-66 16:45

J. Hearn says one of TWX lines drops
randomly chrs.

Bill Overher

8-9-66 THE LPT IS NOW UP BUT

24:00 SEE RANDY BEFORE USING IT

IF ~~IN~~ ~~NOT~~ HERE YOU MUST TAKE
YOUR CHANCES WITH IT

I HAVE HAVE MADE A BELT?

IT MIGHT WORK 4 HOURS OR 4 MONTHS

IT ISN'T CLEAR YET.

Randy

More ->

.K

NO. 4

8-9

0900

9th Aug 66

01426.4

SYSTEM REINITIALIZED AT 2359:00, 25-JUL-67

CORE PARITY ERROR, LOCATION 000000066115 OPND = 775777046123
PC = 750000023052 INSTR = 2460407777773
DATE = 000636551005 TIME = 0000:47

CORE PARITY ERROR, LOCATION 000000066115 OPND = 775777046123
PC = 750000023052 INSTR = 2460407777773
DATE = 000636551006 TIME = 0001:58

CORE PARITY ERROR, LOCATION 000000053715 OPND = 577777033716
PC = 350000021060 INSTR = 346540001134
DATE = 000636551013 TIME = 0007:02

CORE PARITY ERROR, LOCATION 000000066115 OPND = 375776046123
PC = 350000021417 INSTR = 322340001444
DATE = 000636551014 TIME = 0007:21

SYSTEM REINITIALIZED AT 0008:00, 26-JUL-67

Handwritten notes:
LPT
SIX
IF
YOU
1 H
IT
IT
HAVE
was
close
NOW
you
ing
ST
Bolt
at 4
Kenny

THERE WAS A BUG IN THE LPT

CORE PARITY ERROR, LOCATION 000000074335
PC = 350000021432 INSTR = 322340001457
DATE = 000636551047 TIME = 0035:07

SYSTEM RESTARTED AT 0039:00, 26-JUL-67

SYSTEM REINITIALIZED AT 0043:00, 26-JUL-67

CORE PARITY ERROR, LOCATION INDETERMINATE
PC = 750000000002 INSTR = 550640000013
DATE = 000636551110 TIME = 0103:26

CORE PARITY ERROR, LOCATION 000000066175
PC = 7500000022730 INSTR = 246040777773
DATE = 000636551130 TIME = 0120:22

CORE PARITY ERROR, LOCATION 000000070515
PC = 7500000025265 INSTR = 322200005305
DATE = 000636551177 TIME = 0158:28

SYSTEM RESTARTED AT 0203:00, 26-JUL-67

OPND = 777773054336

Jul 26, 1967 2:30AM

When I came to work on PDP-6, the ~~page~~ messages on this page to dotted lines had been generated. The system was not working, and core 0 had "error" light on, which went off after I pushed reset button. After I restarted at 143, I got the last message on this page, and the system was still unresponsive. I then tried restarting by loading 16K dump etc. and got nowhere. I finally loaded the sim loader, 16K dump, etc and again got nowhere. The "par" light is off on core 0 but no amount of pushing reset buttons will turn off the parity light off

Richard Seely

OPND = 050512050511

0900

9th Aug 66

01426.4

DATE = 000000000000 TIME = 000000000000

DATE = 000000000000 TIME = 000000000000
BC = 000000000000 INSR = 000000000000
CORE BARELY ERROR, LOCATION 000000000000

DATE = 000000000000 TIME = 000000000000
BC = 000000000000 INSR = 000000000000
CORE BARELY ERROR, LOCATION 000000000000

DATE = 000000000000 TIME = 000000000000
BC = 000000000000 INSR = 000000000000
CORE BARELY ERROR, LOCATION 000000000000

DATE = 000000000000 TIME = 000000000000
BC = 000000000000 INSR = 000000000000
CORE BARELY ERROR, LOCATION 000000000000

DATE = 000000000000 TIME = 000000000000
BC = 000000000000 INSR = 000000000000
CORE BARELY ERROR, LOCATION 000000000000

DATE = 000000000000 TIME = 000000000000
BC = 000000000000 INSR = 000000000000
CORE BARELY ERROR, LOCATION 000000000000

DATE = 000000000000 TIME = 000000000000
BC = 000000000000 INSR = 000000000000
CORE BARELY ERROR, LOCATION 000000000000

DATE = 000000000000 TIME = 000000000000
BC = 000000000000 INSR = 000000000000
CORE BARELY ERROR, LOCATION 000000000000

DATE = 000000000000 TIME = 000000000000
BC = 000000000000 INSR = 000000000000
CORE BARELY ERROR, LOCATION 000000000000

DATE = 000000000000 TIME = 000000000000
BC = 000000000000 INSR = 000000000000
CORE BARELY ERROR, LOCATION 000000000000

[Faint handwritten notes and bleed-through from the reverse side of the page.]

more - 1

THERE WAS A BUG IN THE LPT
BESIDES THE BROKEN BELT.

THE COOR WHEEL (CHAN. (1)) STR.
WAS SHORTED OUT IN THE CABLE ASSM.
IT WAS THUS IMPOSSIBLE TO PRINT
ANYTHING AS THE TIMING GENERATOR
WAS NOT BEEN GROKED.

THERE WAS AN ATTEMPTED BY ANELEX
TO SHIELD SOME TW. WIRE IN A CABLE
BY SOLDERING SHIELD SLEEVING ON
BUT THE HEAT OF DOING IT BROKE
THE INSULATION DOWN
GOD DAMNED ANELEX AND THEIR Q.C.

8-10 POWER ON J.L. 1444.9

8/10 TTY 5 doesn't see 'Shift' on numerics
and some other keys²

J. Sauter

8-11 PWR ON J.L. 1463.0

RESTORED INTERLEAVE ON 1665 MODULES FOR 167

8 pm Power on 1473-5
R.D.oran

8-11 2145 System giving mysterious
nasty messages. Reloaded several times.
No help.

RAN BLT - ok

RAN CONS. gave error message

(enclosed) RAN UINS3 - ok

RAN UINS4 - ok

RAN UINS5 under TS - ok

John Sauter

8-12 PWR ON

1486. J.L. - BW

Belt for printer arrived & was installed.
The 167 would not address ~~core~~ even core
locations. The I/O states of bit 35 were not
furnished to the 1664 modules. We found they
were tied to bit 27. They were moved to MA BIT
35. The 167 now talks to interleaved mem. OK.

8-12 6:30 AM

PUT NEW 13" RIBBON ON LPT
SHOULD SOLVE MISSING LEFT COLUMN

ANELEX # 87728 IS THE RIBBON

WE USE FROM NOW ON

RANDY

8-13 3:00 AM

Line Printer was not receiving "2" bit
from controller. Upon wiggling wires
going into 50-pin Amphenol plug, the
problem went away & I could not
get it to come back.

Phil

8-13 --- 2145

Fixed LPT bug, whereby

first char. after EONO is printed

as after a DELETE. It was another

C.F.H.S.

~~C.L.Q.~~ DAMN DEC DESIGN DEFICIENCY!!

SAE ~~646-10-7~~ 646-10-7.

D. Poole

5:10

8-14-66

TTY7 seems to drop subouts

Orbach

8-15

J.L.

1550

RIM loader would NOT load PAPER TAPE

Loc. 26 = 71040 — BIT 12 NOT GETTING TO CORE, RESEATED 6205A IN 2DE19. OK NOW.

8-16 1800

DTA 1 Bounces a lot
XPR

8-16 2052

System died with parity error in

Mem Loc 100050₈ PI 7 ~~active~~ in Progress

Did following:

1- Instr. Stop

~~Parity error~~ 2- Clr Error - Parity Chkr

3- Restart - " "

Then

tried action A in operating Manual with no luck

tried " B no luck but PI 7 went off this time

tried " C no luck this time ParEr. @ loc 44₈

tried " D Parity again

I. Sobel

8-17

ADJUSTED 'LONG' STOP TIME ON DTA 1

J.L.

1594.7

8-17 -66 1325

DRA 4 floppy tape
around and bounce

RR

8-18 1618.0 JL

RUNNING TS MAIN (PT 1, 2, 4 & 5) 9:30 AM

8-18 SYSTEM UP 11:25 AM

8-18 LPT IS FEELING PRETTY BAD
WHEN YOU TRY TO DO A LISTING
AND ITS ON LINE THERE'S A 50-50
CHANCE THAT IT WILL IGNORE YOU
AND DO NOTHING IN THAT CASE
YOU HIT START → STOP → MANUAL PRINT
→ RESET IN THAT ORDER 15 TIMES
TO GET IT TO LISTEN TO YOU AND
START PRINTING, IT WILL RUN FOR
ABOUT 2-3 PAGES AND STOP
RANDY

8-18 - RAN PRINTER FOR 20 MINS. (OK) J.C.

2040 8/18/66

"STOP" command to DTA1
appears to not work occasionally.
it sometimes free-wheels for a while.
(happens under 2.4, 2.6+
DEC DUMP)

John Sauter

18 AUG, 66 2100

TTY5 prints (for * occasionally
They are adjacent on the print wheel
and they occasionally) is
printed, so it looks like the
mechanism needs oil or something

JRR

8-18
1030PM
Air Conditioning WANTS TO WARM US
Now, Temp IS 81, WHAT IS
going on —

DTA2 hrs up would not turn

which

Line Printer still has some
trouble as last night
Bill Weck

8-19 0945 PWR UP 01637.8

WTH

MONITOR RUNS LPT OK (AT THIS TIME) BUT
PRINTER DIAGNOSTIC TYPES ~~OUT DONE FLAG~~
"NO DONE FLAG FROM LPT" AFTER DOING CORR.
RETURN & FORM FEED. (PROGRAM BUG?)

8-20

3:00 Printer entered lose mode 87°
Ok at 85 earlier

TTY5 does not seem to work OK NOW
J.L.
Wick
Wick

August 21 11:45. AM

Line printer showing same problems as
described under 8-18 by Randy.

John Sauter

8-21 CORE Two (2) Hung ARQ "O"

Randy

8-23-66 PWR ON 1722.6 J.L.

FOUND PRINTER WOULD NOT COMPLETE PRINT OF
A LINE OF ALL PRINTABLE CHARACTERS; IT WOULD
CONSISTANTLY FAIL TO PRINT LOWER CASE P, R & Q
REGARDLESS OF THEIR POSITION ON THE PRINTED LINE.
FOUND THAT, DUE TO MISALIGNMENT OF THE LAMP

Assembly Fair The 8 channel code wheel, three pulses of channel one photo diode were less than half the amplitude of the rest of the pulses. Realigning the lamp assy. brought equal amplitude of the 128 pulses.

8-24-66 PWR STILL ON 1749

8-25-66 PWR STILL ON 9:30AM 1771.6

8-25 16:40 J.L. 1779.0

LOADED OLD MONITOR (2.4M) AND RAN UINS48

UINSS 15 MIN. (OK)

RAN TS MAIN 15 MIN (OK)

RAN BLT 25 MIN (OK)

8-26 0920 J.L. 1795.0

RAN DecTape Test EX DATA (OK) DECTEST (OK)

Dly Times 36.0, 184, 290 MS.

CONS TEST 10MIN. (OK)

MEMORY TEST (FAST) (OK) 15MIN.

REPLACED ALL AIR FILTERS

LUBED TTY 7

8-29 0920 PWR ON 1861.6

8-30 0915 PWR ON J.L. 1884.0

INSTALLED PARITY IND. PANEL IN CORE 0

Aug 30

Tape Drive 1 seems
bad. Seems to be very weak motor.
Field.

~~System~~
CPU hung only intercess light F6A
pushy stop-continue fixes the world

19 25 30 Aug 66

SF5A lamp on CP is always on.
bad driver?

SRR

CP hung In User Mode PT cycles
at various places. See picture for
one example. It appears that RD RS
is not getting through to
CP from some (maybe all) memories &
happened 3 times

SRR

8-31-66

TTY6 control key and altmode
stuck

OK now
J.L.

Weir

0300 31 ~~Hour~~ Aug 66

Stop on ERROR Switch on
parity box has no effect

TTY5 Prints wrong character

* as (or Q
etc.

N as K

N as -

mostly at beginning of line

SR

31 Aug 1966 ~1600

PARITY ERROR Location 025152.

(examine switch showed it really is there. Deposit
ZERO cured it)

John Sauter

31 Aug 1966 1630

System doing funny things to dec tapes.
It hangs in chan 7 at the end of a record.
pushing a character on the console TTY
restarts it.

Ran DECTAPE TEST.

UTEST	ok	} unit 4
DCTEST	ok	
EXALL	ok	
EXDATA	ok	
EXDATA	ok	unit 3
UTEST	ok	unit 6

Got error 72 from dectape test
claims it is a spurious interrupt
didn't happen

~~Root~~ Found IO Bus terminator
cards pulled — system OK
Replaced them. no troubles
JRR

1930 1 Sep 66

Teletype receiver #0 drops bits
when receiving from dataphone
typed received typed received
3 → ; 8 → =

SR Russell

2335 3 Sep 66

Found cable from parity box to
switches was unplugged subtly. Fixed
it and now stop on parity works.

~~The connector can be to the~~
short Amphenol connector that plugs
onto the back of the switch panel
can be plugged in shifted off by
1/2 a pin. It is invisible from the
back and the side, and the
top and the bottom is invisible
Amphenol made a connector that can
be plugged in wrong, and it was

were
the ~~are~~ also some random hang-up
of the system in F6A an IF1A that
appeared to be RD RS getting lost between
~~on the~~ somewhere between memories and
the CP. This bug has not stood still
yet.

LRR

0405 5 Sep 66

CP hung waiting for RD rs from
core 0. It had gotten the instruction
from 44 (core 0) on a seq lb
but it had not gotten out of the
Mem Ctl sub-routine.

IF1A was lit

LRR

0420 5 Sep 66

AGAIN


LRR

0421 temperature rising
again only in core 1, core 0, core 3
core 2 - it seems to want a hot
machine

9-6-66 PWTRON. 0915 J.L. 2015-3
RAN TS MAIN PT. 1, 2, 4 & 5 1/2 hr. (OK)
RAN BLT 1 HR. (OK)

Replaced LAMP DRIVER FOR SFSA INDICATOR.
ADJUSTED COL 37 & 62 ON ANELEX PRINTER
(WERE MAKING VERTICAL PERIODS.)

9-6-66 23:37 EXPANDED THE HUB SPRING ON DTA1.
THE REELS DON'T SLIP NOW SEE BELOW



Randy

0300 9-7-66

PUSHED IN ALL MB CONTROL AND MA
CONNECTORS BETWEEN CORE 0 and CP
IN HOPE OF SCARING THE NO RDRS BUG
NO EVIDENCE RESULTED.

ARP

0900 9-7-66 J.L. PWTRON 2026-1

LOOKING FOR RDRS BUG. FOUND COLD SOLDER
JOINT ON 1664 BOARD (1BC1 IN 167) PINRY. ALL
SOLDER JOINTS LOOKED GOOD ON RDRS LINE. CHECKED
BOARDS IN 162 - 169 & CORE FOR THIS SIGNAL.

9-8-66 0200

RDRS BUG or something like it
also PARITY ERRORS, but machine stopped
even though the "STOP ON ERR" sw
was in the GO position.

RESTART worked as if it was
stopped -

??

TTY5 GARBAGES CHARACTERS ON OUTPUT.

Printer pulled ribbon off lower
roll.

SRR

ARM PUT RIBBON BACK ON LOWER ROLL.

DTA1 FULL OF STATIC OR SOMETHING.
FIRETEAM WOULDN'T READ THE TAPES.

DTA4 SQUEEKS

RANDY FIXED SPRING ON DTA1. NOW TRY
TO GET A REEL OFF.

9-9-66 0230

TTY5 doesn't work
keyboard locked. ~~no~~

OK J.L

SRR

9-8-66 1945

NO RDRS AGAIN!

MC RD

IF1A

John Sauter

9-9-66 0420

Printer printing for blank
and o for blank (see sample)
it is warm.

SRR

9-9-66 0445

Printer hangs
RESET will unhang it
start it and it hangs again

this time STOP will work
and manual print will clear it

START STOP MAN PRINT ~~works~~

for several times makes it work
again.

SRR

446

9-9-66

Printer pulled ribbon off bottom roller.

SRR

0515

9 Sep 66

the hang up in the printer
(see 445 today) seems peculiar to
F4's initializing code. a program
that gets stopped and restarted doesn't
seem to hang up the printer
More spurious characters

SRR

90-Sep-66

TTY1 has lousy chus
they type wrong + system hears them
wrong (system hears different than those
printed too)

Wether

1600 10 Sep 66

Found printer bug - the collar that holds the photo-diode assembly was still loose it moves slowly. When it is out of adjustment, it prints occasionally as P etc. ~~It does not~~ it is not possible to tighten down the holding clamps because of analyzer's clever construction.

SRR

9-10-66 1500

Camera is ^{still} writing bad parity words

in core

LOC5 035020

200000

SB

9-10-66

The problem where TTY 1 sends bad characters appears to be in the 630 because any TTY which is plugged to Line Patch $\phi 1$ does it.

Phil Peterson

1707 40 Sep 66

Got a special Allen wrenches - tightened down the dogs that hold the collar that holds the photodiodes and lamps. ~~Tightened down the~~ Doesn't help. the collar still moves
FOO!

SRP

4-10-66

WE NOW HAVE (2) TWO FULL TIME BABY MOTHERS
(WIND UNITS) I LOWERED THE CUT IN PRESSURE
SO IT WILL RECYCLE ON ONLY BY THE STAT.
I CALLED CARRIER AND THEY AGREE

Randy

30-JAN-67 0545

The scope is acting funny. It seems to shrink to smallest character size and no spacing occasionally, almost as though it were losing the GLF bits. To observe this, run CLOCK, on DTA7.

J. Senter



9-10-66

- 1) DTA1 runs tape off when attempting to directory sometimes
- 2) 910-373-1799 unable to communicate with system
- 3) 910-373-1776 gives spurious return (on echo mode) every so often

CP Clark

9-11-66

The line printer blew the blue grasshopper fuse in the lower left corner of the panel, (twice), (the other fuse goes just above it).

Phil Peto

THANKS FOR NOTHING! NEXT TIME LEAVE THE DAMMED FUSE WHERE IT WAS AND GIVE COLUMN ROW INFO WITH THE STATE THAT THE ANELEX PRINTS ARE IN, ITS ~~VERY~~ NECESSARY THAT YOU MAKE VISUAL OBSERVATIONS ONLY, NOTING WHAT YOU SEE + WHERE YOU SAW IT!!

RANDY

Jim Lyons

THERE IS A MYSTERY AS TO THE FUSE
FUNCTION SEE ME MONDAY ABOUT THAT
AS PER OUR PHONE CALL Randy

2200 11 Sep did a check on TWX connections
1799 works OK. I suspect that
2.6.6 had forgotten about it.

1776 sat for several minutes
without typing out anything. - perhaps
a system bug, or else it depends on
lots of other things going on

JRR

Power off 0445 12 Sep 66 JRR

POWER ON 0930 12 Sep 66 2132.0 JL

9-12-66 1100 Was using Macro^{ist} after calling it
2.6.6 Printed Parity Error L6C 200000

Pushed Restart on Parity Box - system died in XEX mode
System restarted from 1400

J Sobel

9-12 J.L.

2135

Replaced MTR. DRIVE BELT ON TTY 5.
Replaced BOTH BRAKE & CLUTCH 3 AMP FUSES
ON LINE PRINTER. PRINTING & ADVANCING
PAPER OK NOW. BUT Paper puller Solenoid
WILL NOT ENERGIZE.

9-13 JL POWER ON

2152.0

RAN TS MAIN 45 MIN (OK)

RAN BLT 45 MIN (OK)

RAN DECIPHER TEST ON DTA 1
(EXDATA) (OK)

PAPER PULLER NOW WORKS. FUSE APPARENTLY
WAS LOOSE IN ITS HOLDER.

THE LAMP & PHOTO CELL MOUNT IS NOW LOCKED
DOWN. THE SPRING INSIDE THE LOCKING BRACKET
WAS TOO SHORT. INSTALLED SMALL SPACER.
(THANK TO FAX I KIT)

9-13 ACFT Power on 2245

9-14 ACFT Power off 0255

9-14 PTR ON 0920 2170.2

TRIPD CONS TEST. CONS TP WAS NOT BEING
GENERATED. Replaced TRANSISTOR (CIRCP) OF

IK18. CONS TEST COMPLAINS AFTER RUNNING

A SHORT WHILE. WILL CHECK FURTHER J.L.
BIT 25 IS BEING PICKED UP IN RIGHT HALF
OF FINAL CONTENTS OF E.

7-15 SOMEONE OF ~~THE~~ JOHNSON CONTROLS DID A
BAD JOB ON ONE TEMPORARY SPLICE INTO THE
AIR LINES.

THEY TAPED THE JOINT UP BUT IT STARTED TO LEAK

ABOUT 2400 (9-14). THE LEAK CAUSED ALL
DAMPERS TO GO FULL HOT (100°F)

WOW

I PATCHED UP THE LEAK, ITS ALRIGHT NOW
Randy

PWR ON

915

0925

2185.0

16 Sep 66

12:27 - DING DING - PARITY ERROR LOC 200000

TTY 5 PRINTS INCORRECT CHARACTERS ON
LEFT SIDE OF PAGE. J. L. R

9-16 2200

DEPOSIT and EXECUTE fail to read

data sw. 19-35. 0-17 are read

correctly. J. Pool

Checked trouble found of O. Poole
problem seems to be in the 6615 in 2H515
pulse MBRT < AR(1) does not happen or at
least never gets to SC ON the back.

Weiber

Pulled board out and put it back
OK. now.

Weiber

9-17-66 1700

Memory Checker board doesn't run.

MB₂₉ goes away. Sometimes in memory store,
more often in AC store. Shut off air conditioning.

1730: bit 29 still goes away.

1800: now bits 23+29 go away. All
~~recently in AC.~~ in AC, 23, 26+29 in
memory. Power Off.

J. Lauter

9-17-66 2130

Found cold-soldered jumper on

pin SC of 2015 (S.No. 0119094).
System works.

D. W. P.

9-18-66 1403

Parity Error Location 47111

Ding, Ding!

J. Sauter

9-18-66 2039

Parity Error Location 1610

POWER ON 9-19 1L 2243.0

Teletype	PWR	CONN.	(AT REAR OF TTY
3 - YEL.	} CONN. FOR 33	} CONN FOR console TTY	3 - Red
4 - Red			4 - WH. GRAY
6 - GRN			6 - WH. YEL
7 - BLK.			7 - BLK

PICKING UP BIT 11 IN CORE 2.

TRIED REPLACING SENSE AMP & INH. DR. TROUBLE

WENT AWAY BUT WHEN ORIG MODULES WERE

REPLACED, TROUBLE WOULD NOT OCCUR AGAIN (?)

REMOVED TTY 5 TO GO TO OFFICE FOR REPAIR.

9-19. ADJUSTED 'LONG' STOP TIME ON DTA1
TO PREVENT TAPE TAPE COMING OFF TAKE UP
Reel.

LUBED TTY 3 2248.1

CONS TEST OK NOW.

9-20 PWR ON 2263-X


RAN BLT .5 HR. (OK)

~~6:00~~

2030 20 Sep 66

TTY #3 makes funny sounds
and won't send correct characters
to the computer. (OK J.L.)

KRR



0100 21 Sep 66

Parity error PMA
core 3 ~~to~~ 120001
DATA = 0

ARR

0100 21 Sep 66

mysterious monitor bugs in lisp, etc.
~~part~~ could be due to core
or dec tape problem when
machine is cold. also could be
program - but not likely.

ARR

0410 21 sept 66

Take-up reel on DTAB seems
out of adjustment. Please check.

ADJUSTED 9-21 - JL

J. Santer

9-22 PWR STILL ON

2310.0

TTY 5 HAS BEEN REPAIRED, OK NOW (JL)

TTY 3 - ADJUSTED DRAGGING CLUTCH, OK NOW

9-22-66 11:40

NO RDRS

IF 1A

~~OP~~ PAR BOX MA = 100320 Box 3
MB = 336002000407

CP: PC = MA = 322

IR = 0

EXEC MODE, CH7 ACTIVE

CP MB = PAR BOX MB

ALL CORE BOXES + PARITY
BOX LOOK HAPPY.

J. Sauter

100

9-23-66

Power off

SPD

9-23

PWR ON

2324.1

2310
2324
10

9-23-66 1810

System died and wouldn't load. READ-IN loader wouldn't work. Putting (710600)60 IN the switches and pushing the XCT key did not turn on the BIN or BUSY lights on the "tape reader". I suspect the I-O bus. There had been a power problem before (Power failure). However, the ~~power~~ problem (system dying) happened before the power failure.

DEPOSIT of 710600000060 and re-examine gives good data so the KEYS, AR, MB & MI work.

John Suter

↑ BAD ⁶¹⁵⁵~~7655~~ in IH9 (HWT).

Replaced. D. Pook

DTA1 doesn't stop
CP trouble appears fixed
2. 6/7, and UINS4 & UINS5

LRR

0415 24 Sep 66

Power off 2443.1

APR

1730 9-24-66

System died under mysterious circumstances. PI 1, 2, 3 + 7 ~~active~~, NON-EX MEM, and running part of the time ^{in progress} in user core in EXEC MODE! Ran Cons TEST. IT waited a while then started printing continuously. Let run about 1/2 page. it is enclosed.

Ran TS MAIN, switches 1-4 up. Punch and reader test (switches 7+5) worked OK.

1800 - Left TS MAIN Running while going to dinner.

1930 TS MAIN STILL RUNNING without any error messages. Loaded 2.6/7.

Runs OK NOW. 1950.

John Lantee

0055 25 Sep 66 Power off 2354.1
CHB

0130 25 SEPT 66

Power on. Core 2 come up
with AW RQ off (evidently).

D. Poole

~~9-26~~ 9-26 PWR ON. 0915 2374.4

Replaced 2894 ON 149 (6155) CIRCLX
ORIG. MODULE REPLACED (OK NOW) J.L.

9-26 COULDN'T FIND HARDWARE LOG.

9-26 FOUND HARDWARE LOG

NO HV ON PRINTER STATIC ELIMINATOR

SUSPECT FRIED INSULATION ON LEAD FROM

HV SUPPLY.

JRP

9-27 PWR ON 0930 2395.8

DTA1 - SNAPPED RELAYS K2-K6 & K4-K7
TO ELIMINATE COASTING WHEN STOPPING FROM
REVERSE DIRECTION.

2130 9-27-66

MI bit 9 doesn't light. tried
changing bulbs - still doesn't.

John Sauter

8900 PWR ON 9-28-66 2416.8

RAN DATA COMMUNICATION TEST DIAGNOSTIC.

FOUND 4706 FOR TTY CHANNEL 1 DROPS BITS
INTERMITTANTLY. REPLACED WITH SPARE. OK NOW.

9-28-66

2444.0

FIX MEM STOP&MEM CONTINUE PROBLEM BY
REMOVING CLAMP LOAD ON IM15 (PIN 2) ON
PRINT-MEM. CONT - 166-0-MC-2

9-29-66 PWR OFF 2300

WJW

10-2-66

Core 3 hangs with RRQR & P2 active

AWRQ off trouble is intermittent

possibly relate AR \rightarrow MD does not clear

bit 22

both troubles suddenly went away
suspect machine cold

Wieber

10-2-66 1550

Tony Hearn, running remote, complained of "cold machine" errors. Specifically, ILL UO at user 60 in a program that had been running all right. Honeywell said $< 70^{\circ}$. I turned Johnson from 65° to 72° . Honeywell started to rise but Tony had to log off right away.

John Sauter

10-2-66 1700

Line printer out of paper. Couldn't find the spares. Got 5 boxes from Comp Center.

John Sauter

10-3-66

2511.2

10-3-66 1300

System died with HALT in the IR, PC=5652. Examine (5652) revealed A just without a halt bit. Pushed continue, system started up.

John Sauter

10-3-66

Temp 62°

2519.0

RAN DATA Comm. TEST on TTY 0, 283. (OK)

RAN BGT FOR 1 HR (OK)

10/6/66 2105

ACTION TO INHIBIT CLOCK INTERRUPTS:

GROUND 2M12S (INPUT OF CLOCK PG)

OR PULL MODULE 2M12 a 4410

CPU ILL OP BUG, SEEMS DUE TO
BIT 22 OF LOC 241 GETTING ZEROED -

MAY BE SOFTWARE

IT WAS!

WORD SHOULD BE

700340 631 ~~XXX~~

word is 700340 ~~611~~ 000

10/7/66 0035

Power off

JRR

10/7/66 11:06

Power on Guam

0-10-66 PWR ON 0900 2627-2

COMPUTER STOPPING WITH IFIA SUBROUTINE
FF. CN. RESEATED Mem. BUS CONNECTORS CN 1664
BDS. EXCHANGED 1665 BD IN IBC9 BECAUSE BUS
CONNECTOR WAS INTERMITTANT WHEN Taped.
APPARENTLY THIS WAS A POOR MATING PROBLEM.

J.L.

10-10

J.L.

2336.5

REMOVED 100 Ω RESISTORS FROM 1B7 & 1B7
4657 TO BUS DRIVERS. (IN LPT 646)

10-10

R.B.

WIRED IN FOR DATAPHONE DATASET.

CONNECTOR IS LAYING ON FLOOR
TO BE INSERTED WHEN (MA BELL) GET
THRU WITH THEIR END

CONNECTED TO ~~THE~~ ^{DATAPHONE} 02 ON PATCH PANEL

10-11

1300

2645

STOP ON FAST MEM CAME ON

WITHOUT APPARENT CAUSE.

RRR

10-11

21:20

Teltype interface #2 doesn't
work well on input from DATA SET connections

3 echoes as 5 on the calling machine and F on
other machine

5 as ? and M

9 as ~~?~~ and N

- as ? and K

RRR

10-11

Reboot on JTY7
does not work

Weiler

10-12 0117

RD RS got lost ~~temp~~ Temp -80°
IF1A lit

111 Times

SRR

10-12 0210

Power off

SRR

10-12 907

Power On

K Purple

10-15 1097

PWR ON 2726.9

WTM

10-16

0955

Power on BWP

10-17-66 12:00

00

System printed part of a parity error message, then a full one, then went into Run-Cycle Defer. (AF0). In both cases PC=0 and instr = BLKI 200. System died and had to be reloaded shortly thereafter.

J. Sauter

ECO # 315 INSTALLED IN Core '0' 2769.4

10-17-66 J.L.

ECO # 286 IN FAST Mem.

10-19-66 0130

~~System~~ Machine stopped in the middle of an instruction.

lights on in APR panel: CHF7, CHF5, LCF1, FE4, FE5, SC1, SC2, SC3, SC6, SC7, EXEC MODE, SC0, AR CRY0 FLG, AR CRY 1 FLG, PC CHAG FLG, CLOCK EN, CLOCK FLG, PIA 34.

all others = 0.

all memories look OK, no parity errors,

MB = 37

INSTR = 135

AR = 22004

AC = 1 INDEX = 6

MQ = 37

PC = 3232

CP MA = 6556

PARITY MA = 106554

instruction stop, instruction continue made
the machine go on.

J. Sauter

P. S. Location 3231 = 135040003425

WHY WAS INDEX = 6 ??

J. S.

19 OCT. 2330

Shift ctr failed to count ^{sometimes} pin M of SC8
never changes, but pin L does ^{works if topped.} Replaced SC8
with spare. Fixed.

D. P.

J. R. R.

140 20 Oct 66

Power off

2816.5 ARK

10-20-66

2832.9

ECO # 315 INSTALLED IN CORE 1-2 & 3

REMOVED INTER LOCK SWs FROM CORE 0-1-2 & 3

ECO # 299 INSTALLED IN 166

ECO # 282 INSTALLED IN 551

0035

21 OCT 66

Power off

RRR

#67 (TV) now works on
water cooled only.

RRR + DT

10-21-66 PWTR ON

V.L.

2834.0

10-22-66 PWTR ON

BWP.

00:21

10-23-66 14:00

The line printer quit working.
After extensive testing, it became
apparent that the problem was in the
"Multiple Output Power Supply." There is
110 V. going in + nothing coming out.

The output at the secondary of the
Transformer seem to be low but
since none of the ^{God damn} drawings indicate

What they should be, it is impossible
to tell. We will leave the printer
apart to facilitate its being fixed
by someone who can read minds better
than we can!!

R. H. L. L.

10-23-66 1755

166 doing random mysterious
things. System died and would not
reload.

J. Sauter

2020 23 OCT 66

INTERLEAVE SWITCHES!

2 IN CP at 2L 16 & 2L 19

1 IN FAST MEM AT BC 5

They are labeled as to which bits
they affect. All in NORM gives no
interleave. All in INTER gives data

0020 23 OCT 66

gives LOTS of interleave
~~167~~ Data Channel
works properly only in LOTS of
interleave.

ARR

0006 24 Oct 66

LOOKED AT PRINTER.

"MULTIPLE OUTPUT POWER SUPPLY"

APPEARS TO GET 110V ~~OUT~~ INPUT,
BUT GIVE ABOUT $1\frac{1}{2}$ V AT ALL SECONDARIES.
AS NEAR AS CAN BE SEEN THIS PS IS
LIKE ~~DWG~~ DWG 33013 - 3 HAIRY
REGULATORS WITH SCR CROWBARS AND
 ∞ TRANSISTORS. THERE IS

NO WORD DESCRIPTION

OF WHAT THOSE REGULATORS DO
AND IT AIN'T OBVIOUS!

ANALEX DOCUMENTATION (?)

LOSES A GAIN!

ARR

0015 24 OCT 66

LOST RD RS IN IFLA 3 TIMES.

KRP

8:45 24 OCT. 66

Power On

KKP

1855

Report of random operation (they found a tape) but with a new one. 16 DEC 20AR loader moves DEC tape along but won't stop it. Most drastic example was one attempt during which the tape spun off the reel. Tried reloading Handman and lost. End of a perfectly good blind chess game!

Dr. Simulant

2010

Replaced 6206 in 2K10 (PCMA 22)

-- would not set. Machine works

J. Poole

0530 25 OCT. 66

(1 R303, 1R107, 1R401, 1R602)

THERE IS NOW Local Power CLEAR IN THE SCOPE, KLUGE BAY TO SERVE THE SCOPE L.P. A-D/MPX, DAC'S ETC

I HAVE WIRED THE 136 AS FOLLOWS

400 NS → TO THE 136 FOR 2 SECONDS, PRF 1 MCS (JABM)

100 NS → TO ALL FLIP-CHIPS " " " "

THIS IS NOW WHAT WE HAVE → CPA POWER CLEAR V

IT WORKS !!!

IOB RESET V
LOCAL POWER CLEAR
(IN KLUGE BAY)

RANDY

0730 25 OCT 66

THE ELARMO (ELECTRIC ARM MODE 0) LOGIC INTERFACE
IS NOW IN AND MY IOB INTERFACE
IS CONNECTED TO IT

ITS NOT DEBUDED YET, SO IF THERE'S ANY TROUBLE
WITH THE IOB **SREAM!!!**

→ RANDY

P.S. DEVICE CODE IS 420

100 25 Oct. 66

Power On

K Purple

0020 26 OCT 66

MOD 35 TTY STRIPPED GEAR

TRIED CHANGING TO A MOD 33

DIDN'T WORK

"20ma"

FOUND ONLY 10 MA DRIVE ON A COMPUTER

OUTPUT LOOP TO TELETYPE.

CHANGED 4707 AT 636 A1

STILL DIDN'T WORK

CHANGED BACK & FORTH SEVERAL TIMES

Got BACK TO ORIGINAL 4707 and

FOUND 10 MA ON LOOP. IT WORKS NOW.

??

RRR

0020 26 OCT 66

DATA ϕ WON'T RESET SOMETIMES

APR

0430 26 OCT 66

DEVICE 420 now exists

DATA0 420, L SENDS BITS 18-31

OF C(L) TO THE ELECTRIC ARM
CONTROLLER.

EVEN NUMBERED BITS ARE DIRECTION
CONTROL FOR THE RELAY
ODD NUMBERED BITS ARE ACTIVATE.

EVERY TIME A DATA0 420, IS
EXECUTED THE ACTIVE UNITS ARE

PULSED. THERE ARE A NUMBER

OF TIMING RESTRICTIONS IN THIS UNIT

DUE TO OPERATE TIMES OF THE DIRECTION
CONTROL RELAYS, AND THE RECOVERY

TIMES OF THE PULSERS. SEE

BILL WICHMAN FOR A DETAILED
RANDY
DISCUSSION OF THESE RESTRICTIONS

IN THE FUTURE, THIS DEVICE WILL
BECOME MORE COMPLICATED, AND A 20

WILL BE REQUIRED IN THE LEFT
HALF OF L, THE WORD OUTPUT

09:15

10/27/66

2947.5

POWER ON
L. Moray

9:45

10/27/66

TTY 1

types double
characters occasionally

H. Pugh

10-28-66

DTA 6

costs

Weiler

045 10-29-66

LIGHT PEN SWITCH CONNECTED IN PARALLEL
WITH CCW SPACEWAR SWITCH

APR

0215

10-29-66

POWER OFF

APR

1070

10-30-66

POWER

ON 2985.9hr L. Moray

Monitor comes in, will start up, and run until job,
even will say "JOB INITIALIZED" BUT
won't recognize anything further.

Meanwhile, all 7 "PI ACTIVE" lights are on, and
the parity error light on the memory.

power off 11:06 L. Moray

10-28-66 1810

Ribbon replaced on printer.

J. Sauter

1820 29 OCT 66

Teletype #2 has a sticky carriage
return

Teletype 0 ~~has~~ keyboard sends double
characters occasionally.

CTY doesn't work or isn't connected
TTY5 sometimes prints L for 7.

SRP

1955 30 OCT 66

TTY ~~0~~ 1 sends double characters

SRP

DEVICE 420, CONT

As FAR AS IS KNOWN ALL THE OTHER IO
STILL WORKS. T.

JRR & JRB

10-26-66

2939.7

Replaced Bum Multiple output power
Supply IN PRINTER. J.L.
PRINTER R.T. Meter = 1270.9

10-31-66 905

3031.2

Power On

K. Angle

INSTALLED 10-31-66 (35) .3032.5

INSTALLED Console TTY. THE STRIPPED
GEAR HAS BEEN REPLACED & ENTIRE TTY
LUBED.

TTY 7 REINSTALLED & LUBED

TTY 2 - CARRIAGE RETURN PROBLEM CORRECTED

TTY 2 WAS ALSO LUBED. J.L.

TTY 1 CHECKED FOR DOUBLE CHARACTERS. WAS
NOT ABLE TO CAUSE THEM. (?)

163010-31-66

CTY still gives a bad character
first time after setting idle for
a while

B for D
A for 1C
A for C

JRR

083011-1-66

POWER UP SYSTEM

CTY CAME ON WITH LOUD KRUNCH
AND WINNING, SHUT DOWN AS SOON AS
POSS. BUT NEW (NYLON?) GEAR
TRAIN ATE ITSELF UP AGAIN

CALLED DEL - COOLZ

RANDY

3061.5

11-1-66

1376.2

PRINTER DOES NOT COMPLETE CYCLE INTERMITTANTLY
ADJUSTED LAMP ASSY. FOR CODE WHEEL. IT LOOKS
LIKE THE LAMP FILAMENT FOR CH. 7 HAS SAGGED
PRINTS OK AGAIN. J.L.

11-2-66

3076.6

INSTALLED ECO # 283 (PI)

1500 2 NOV 66

MONITOR WON'T GET PAST

" PLEASE TYPE TODAY'S DATE "

11-2-66

3087.8

DecTape TEST WAS RUN AFTER SYSTEM HAD TROUBLE WITH TAPES. IT COMPLAINED THE DELAYS WERE NOT SET PROPERLY. CHECKED THOSE DLYS & FOUND THE DLY THAT USED TO BE 306 MS WAS ONLY 288 MS. HAD TO ADD ADDITIONAL CAP. BECAUSE POT WAS ALREADY AT MAX. RES. RESET ALL DLYS PROPERLY. BUT DecTape TEST STILL COMPLAINED. FOUND 4523 READ AMP FOR MARK TRACK WAS OSCILLATING. REPLACED SAME. BUT DecTape TEST STILL WAS UNHAPPY. FINALLY IT WAS DETERMINED THAT FAST MEMORY WAS AT FAULT. DecTapes LIVE AGAIN. J.L. A 1250 BD. WAS REPLACED IN 162. BIT 4 WAS BEING PICKED UP.

11-3-66

9:30

3099.2

Power Up

Pringle

10:30 Many ILL MEM REF AT 1051 -
can't get anything done

G. Sutherland

11-3

3106.0

Channel 5 output FROM Code Wheel looked very

poor. READJUSTED LAMP IN LAMP ASSY. FOR THIS

Channel, looks OK now V.L.

11-4

9:15

Almost continuous parity errors
(Every minute or 2)

Always seems to be box

11-4

TTY2 sometimes doesn't take new
line on carriage return C.S.

TTϕ gives 2 chrs. for the price
of one also makes systematic
substitution of chrs for a 5-10 chr.
space about 2/3 of way across line

On Weiler

1030 7 Nov 66

FOUND A FUNNY PSEUDO-MISSING
RD RS BUG. PARITY BOX WAS STOPPING
ON PARITY ERROR. EVEN WHEN ^{PARITY} STOP SWITCH
WAS IN GO. RESTART STARTED IT. CP LIGHTS
WERE FLA + NC RD. ~~THIS DO~~ THERE
REALLY WAS A PARITY ERROR BUT THE PARITY
BOX SHOULDN'T HAVE STOPPED. ?

SUGGEST THAT NEXT TIME A MYSTERIOUS
MISSING RD RS APPEARS SOMEONE TRY HITTING
"RESTART" ON THE PARITY BOX. OR TRY
LOOKING AT PARITY ~~1B1E~~ 1B15 N
which SHOULD BE AT -3 FOR ^{GO} STOP MODE
~~GO~~ FOR ^{STOP} GO. STOP ERROR STOP FF
1 = -3 AT 1B12J · 0 = -3 AT 1B12K

APR

1115 11-7-66

Old line printer bug back again - it started happening right after we reloaded paper. START → nothing. STOP → MANUAL PRINT. MANUAL PRINT → Printing part of a line. ect.

J. Sauter

1215 11-7-66

The DC's on the line printer have been re-defined. Now DC0, DC2, DC3 + DC4 have the same effect as vertical tab, and DC1 skips one space (like line feed) but will rem one-line-at-a-time even over page boundaries. This is good for printing pictures that use more than one page - i.e., continuous forms.

J. Sauter

11245 7 NOV 66

ADJUSTED KEYBOARD MECHANISM ON
TTY TO REDUCE DOUBLE CHARACTERS

APR

1330 7 NOV 66

Another pseudo-missing rd side
struck. NON EX MEM was there

FAST MEM HAD STOP TURNED ON.

SOMETHING TURNED IT ON. RESETTING

FAST MEM MADE IT GO AWAY.

APR

Power off 11/8/66 ~~0313~~ 0313 3179.2 hrs.
Lockwood Morris

Power on 08125 - Single 3180.6

LOOKING FOR FM STOP PROBLEM. FOUND PIN K
(THE output of SINGLE STOP SW.) HAD ABOUT 1 VOLT
OF NOISE. ADDED 330MUF CAP. FROM PIN K TO GND
TO REDUCE NOISE TO .2V. J.L.

11/9/66 0045

Line Printer Hanging Up - ^{done} Reset/Start, repeatedly cured
Problem temporarily.

Power off 00:48

Suzuki

11/10/66 02:10 Power Off - no Printer trouble.

Suzuki

15:18

3222.8

11-09-66

PRINTING OF LOWER CASE O INSTEAD OF LEFT PARENTHESIS WAS CORRECTED BY RESTORING THE +6 -6 VOLT REGULATED SUPPLIES TO THEIR CORRECT OUTPUT LEVELS. +6 SUPPLY WAS 5.6 & -6 SUPPLY WAS -5.7 VOLTS. THE -18 SUPPLY SHOULD BE SET AT -17.5. THE EXCITER LAMP ASSY FOR THE G LINE STROBE PHOTO DIODE NEEDED ADJUSTING. (FILAMENT SRG?). NOTICED THAT G LINE STROBE PULSE AND FORMAT PULSE (CHANNEL 8) COINCIDENCE DID NOT STAY THE SAME BUT DRIFTED. FOUND THE VERTICAL FORMAT SPROCKET WAS NOT LOCKED DOWN TIGHT. TIGHTENING THE LOCK NUT CORRECTED THIS PROBLEM. JL

11-13-66

1- DEV DAT ERR FROM MACRO

ON DAT1 EVIDENTLY WAS XMISSION ERR BECAUSE I WON BY TRYING AGAIN

2- TTY PRINTS "1" INSTEAD OF "3" CONSISTENTLY IN COL. 40 WHEN USED WITH "P" COMMAND IN EDIT2 SUSPECT BAD TTY - IT ALSO OCCASIONALLY ECHOES DOUBLE CHRS
 regularly
 I. Sobel

10-13-66

DTAI Giving frequent device data errors in EDITZ

TAPE IS GOOD; Same tape on DTAS gives no errors

J. Sobel

10-14-66 4:45 3299.6

Power on

Pugh

10-15-66 POWER ON J.L. 3316.4

REINSTALLED PART OF ECO # 294

ADDED CLAMP LOAD - 1B14N TO 1B14V

1B09 V WAS MOVED TO W

1B12 V WAS MOVED TO W

RAN TS MAIN 15 MIN (OK)

RAN FAST Mem. TEST (OK)

RAN BLT 10 MIN (OK)

RAN DeCTape TEST (OK)

10-17-66 POWER ON J.L. 3362.3

INSTALLED ECO # 317 IN 166

14-16-66

Was moving TV camera & bit 10 kept going away & thus causing a parity error.

The output of the appropriate memory bus driver P.A. was only about $1\frac{1}{2}$ V. (W102 in F~~7~~⁷). I switched the W102 with the one next to it (F 8), & the problem went away, so it must have been a dirty contact. I looked at it with the scope & the same W102 was now putting out a full 3 V. signal.

Phil Petri

2250 11-18-66 1

Thoroughly investigated TV system
found

- 1) SLOW RETURN FROM WHITE TO BLACK
DUE TO LONG CABLES. LEFT AS
IS FOR NOW. CAN BE FIXED BY USING
SHORTER CABLES TO COMPUTER AND CAMERA.
WILL BE FIXED LATER WITH A VIDEO
AMPLIFIER TO DRIVE LONG CABLES.

2) CAMERA AND MONITOR WERE OUT OF
ADJUSTMENT. SYSTEMATICALLY
RE-ADJUSTED THEM. ALSO
BAPTIZED BILL WICHMAN AS VIDEO
MAGICIAN. VIDEO IS NOW BETTER
THAN EVER. MONITOR IS ALSO
SOMEWHAT MORE HONEST.

WE STRONGLY URGE THAT
THE CAMERA BE LEFT AS IS!

Russell + Wichman

19 Nov.

TTY & types out correctly. Things seem
to be getting into one properly

Purple

02450 LABEL3: SUBR EDGTRT;

STIPQ ML LU EDGE

*I.
02450 LABEL3: SUBR EDGTST;

SKIPO MN VVON NO EDGE

ILR

*P.
02450 LABEL3: SUBR EDGTST;

STIPQ ML NO EDGE

*

2235 19 NOV 66

Power off SRA

1800 21 NOV 66

Turning the ~~REPCO~~ DELTRON POWER SUPPLY
ON THE ARM OFF AND ON GIVES
SPURIOUS INTERRUPTS TO BLT mem
diagnostic.

SRA

1600 dropping BIT 29 in Core ϕ .
Replaced Sense Amps & Adjusted
Slice Level. JJ DEC

~~30-Jan~~

TTY2 still gives 2 chars
for price of 1 IS.

NOV. 21, 1966

HAD LOTS OF BAD PARITY IN CORE "0"
CALLED DEE AND JERRY CAME OVER
HE + I RAN AUTO BLT. AND FOUND BIT 29
BAD, SWAPPED SA'S AND IT MOVED WITH
CARD, ~~PUT~~ PUT NEW "SA" IN 29 AND NOW
IT WORKS

BAD SA WAS IN IH12 OF CORE "0"

3:30 PM RANIDY

NOV 21 1966 FURTHER ON ABOVE

THE MACHINE RAN FOR ABOUT 10 MIN
AND THEN THE WORLD TURNED TO MIAIUBEL
THERE WAS 3 BAD SA'S IN OUR SPARE
STOCK BUT THE (4) ONE WORKED OKAY
+ WE THEN FOUND THAT THE MARGINS WERE
VERY POOR ON ALL SA'S OF CORE "0"

JERRY TWIKED THE POT ON THE SLICE LEVEL CARD
WHILE I RAN MARGINS AND RESTARTED THE PROG.

WE FINALLY GOT $\pm 7.5V$ MARGINS

IT LOOKED GOOD AS OF
22:00 THIS DATE

Randy

2200 21 NOV 66

1000027774 OPND = 021000004000
56000000
= 209: 13

00027734 OPND = 241531022230
6000000
209:(5H\$L31

1027774 OPND = 021000004002
100000
09: 50

7734 OPND = 241531022230
100
02

NOV. 21, 1966

HAD LOTS OF BAD PARITY IN CORE "0"
CALLED DEL AND JERRY CAME OVER
HE + I RAN AUTO BLT. AND FOUND BIT 29
BAD, SWAPPED SA'S AND IT MOVED WITH
CARD, ~~WE~~ PUT NEW "SA" IN 29 AND NOW
IT WORKS

BAD SA WAS IN 1H12 OF CORE "0"
3:30 PM RAI

NOV 21 1966 FURTHER ON ABOVE

THE MACHINE RAN FOR ABOUT 10 MIN
AND THEN THE WORLD TURNED TO MIRRORS
THERE WAS 3 BAD SA'S IN OUR SPARE
STOCK BUT THE (4) ONE WORKED OKAY
+ WE THEN FOUND THAT THE MARGINS WERE
VERY POOR ON ALL SA'S OF CORE "0"

JERRY TWIKED THE POT ON THE SLICE LEVEL
WHILE I RAN MARGINS AND RESTARTED THE PA
WE FINALLY GOT $\pm 7.5V$ MARGINS

IT LOOKED GOOD AS OF
22:00 THIS DATE

Randy

4,LIS\\SPGEN

4,LIS;\\SPIO

RE PARITY ERROR, LOCATION 000000027774 OPND = 021000004000
= 350000020134 INSTR = 251656000000
STATUS = 000000120077 TIME = 209: 13

2200 21 NOV 62

RE PARITY ERROR, LOCATION 000000027734 OPND = 241531022230
= 350000020134 INSTR = 251656000000
STATUS = 000000120077 TIME = 209:(5H\$L31

RE PARITY ERROR, LOCATION 000000027774 OPND = 021000004002
= 350000020134 INSTR = 251656000000
STATUS = 000000120077 TIME = 209: 50

LC*
4,LSPRUN

4,LISPWT

RE PARITY ERROR, LOCATION 000000027734 OPND = 241531022230
= 350000020134 INSTR = 251656000000
STATUS = 000000120077 TIME = 213:02

NOV 25 1966 4:30 PM

CORE "0" TUNED TO SHIT !!!

MARGINS HAVE CROSSOVER

AUTO BLT SHOWED 20D+A 21D+A 18D 34D


WILL CALL DEC MON. MAY HAVE CORE TUNED UP
BEFORE WARRENTY EXP.

FOR TIME BEING WE BYPASSED CORE "0"
AND WE ARE OUT OF INTERLEAVE

RANDY

MORE ON CORE 5:00 PM

P2 1664'S HAVE BEEN SWAPPED BETWEEN CORES



AND C"0" (WHICH NOW HAS C"3" 1664) HAS BEEN
PUT ON P0 ONLY RQ
WHICH MEANS NO CAMERA

FURTHER, 167 AS BEEN DISABLED

RANDY

Nov. 26 1966 7:00 A.M.

I traced the core problem to a 1996 module in IL1 by the fact that the bad parity always occurred in addresses which went through that memory driver. I replaced the module & the box worked fine.

I re-interleaved the machine & switched the bed-sheet boards back.

It is interesting to note that while the boards for box 0 & box 1 are numbered C0 & C1 respectively, the ones for boxes 2 & 3 are numbered C3 & C4 respectively.

I tested the camera & it works.

Phil Peto

Nov 28 1966 0700

CORE "0" STILL BAD R+W SEEM OFF + SLICE - SA'S

MARGINS STILL BAD CALLED DEC WILL COME TUE 27

0400 29 NOV 66

ABOUT 15:00 28 NOV 66 LPT & DT'S WERE
reported acting up

Tested Core with 5 m of BLT - OK

~~Test~~ TSMIN 6 MIN - OK

LPT test hung up

DT test - it is normal to have

CPA/ ILL OP UP IT TURNS OUT,

SOME COMPLAINTS ABOUT DATA

CONTROL - 136 WENT AWAY

WHEN TEMPERATURE CHANGED - MAYBE

BACK TO PRINTER -


FOUNT LAMPS FOR CODE WHEEL

MISSALIGNED. BENT THEM INTO

ALIGNMENT.

I SUSPECT STRONGLY THAT VERT
FORMAT LIGHTS ARE SIMILARLY OFF,
BUT I'M NOT SURE.

FOUND ONE PRINT HAMMER ASSEMBLY
WITH A COIL COMING APART, BUT IT
STILL WORKS OK.

ALSO FOUND THE PAPER PULVER
BELT IS BRAYING 

0400 29 NOV 66 Power off SKR

01100 29 NOV 66

DEL WAS HERE, RAN A COMPLETE
PM ON 6 (SLICE CORE "0" LOW) → (MADE SOME BITS)
(NOSEY)
DTA'S SEEMS FULL OF VIM + VIGAR

INTEST OKAY, BLT ✓, MEM CHECKER ✓

CORE MARGINS $\pm 5.5V$ ON LOGIC $-7.5 + 9$ SA'S

ALL CORES $\pm 3\%$ ON ABOVE

ONLY THING THAT WE DIDN'T ADJUST

WAS LPT, IT RAN VERY FUNNY AT TIMES

LOOKING FURTHER INTO IT - - - - -

GETTING SPARE BELT

HAMMER ASSEM.

AND WRITE UP OF LPT TEST

FOR OUR UNITS -

RANDY

NOTHING CAN GO WRONG!

1400 29 Nov 66

DTA 5 left Hub scrapes base plate

DTA 6 left Hub very tight

[Signature]

0200 30 NOV 66

MADE DTA 6 LOOSE

Randy

2215 1 DEC 66

TTY 2 SENDS 2 CHARACTERS
OCCASIONALLY (ESP. COMMAS)

[Signature]

2350 1 DEC 66

~~System~~ System has hung up ~~two~~ 3 times
in a channel 1 PT. 2 times with
power on ~~was~~ AD and once without power on A-D.
Therefore A-D is not problem. the system
seems to be in a tight loop in
the first few words of ~~aprs~~ APRSER
single stepping through the code stops
this after a while.

It seems to be a bug in APR PI
or PI system or maybe in
DECTAPE control or 136 #1 PI'S


ARR

0025 2 Dec 66

TTT? ~~cont~~ CTL key is
loose and low. ~~if~~

ARR

The Calcomp Plotter is hooked up &
working. It may be used as follows. There is
a switch above ^{to the left of} the meter on the panel above the
paper tape reader. Turn it to the "calcomp" position.
Now the Calcomp replaces the punch & every
character sent to the punch, goes instead to
the plotter & is interpreted as follows:



AWAY TOWARD

12-2-66 7:00 A.M.

The machine no work.

The trouble started when I put the console "table" back into the machine. Checking showed a wire broken & severed with insulation scraped off. I fixed these. They were in the cable to the indicators on the front panel.

The "PI in progress" light for channel 2 remains on although the flip flop is off. The machine hangs up in a way which indicated a pulse is being lost somewhere. I can find no other cable or plug problems. I am very tired. I am going home. Shit Shit Shit!

Good luck

PH W

12-2-66 8:00

Can't start test pd. 3 - held @ 754 - "Clock failed to turn on"

12-2-66 10:00

Problems. I/O B:IT 26 Lost. Found on 50 Pin Cannon Plug at 2L26.

MEMORY STOP and Repeat do NOT work. Turned Cable 180°
MEMORY STOP still does NOT work. Repeat is OK.

PI 2 still NOT working properly.

JPS
DEC.

12-3-66 : 12:00 noon.

PI Encoder Bad. Causes Interrupt on Channel 1 To go To Loc 46.
Replaced Transistor on G129 at 2N06.

JPS
DEC.

~~12~~

2130 2 Dec 66

Changed Printer ribbon

JPS

2200 2 Dec 66

Fan in Bottom of bay 2 has intermittent

power wire

JPS + DP

0000 3 Dec 66

Another PI system bug
of PI ch 1 doing PI ch 3 code
in the system. This should
have been fixed by replacing the
transistor in the PI system

0900 3 Dec '66

Occasionally the system will hang with
chan. 4 in progress. It does not seem to
be correlated with any piece of I/O gear. Within
about a minute the condition goes away and the
system starts running again as if nothing had
been wrong.

J. Sauter

1915 3 DEC 66

Troubles with system BIT 22
of AR or AC 0 ~~keeps getting~~ stays
on for TSCN + INDEX AOPS
SAYS PT 1 of instruction test.

After numerous stops with bit
22 being 1 when it shouldn't or
equal zero compares failing, PART 1
of INSTRUCTION TEST works

Suspect bit 22

we are going to eat-

Will be back

SRR


2110 3 Dec 66

INS TEST PT 1 RAN OK for 2 hrs

SHOULD TRY MARGINS ON AR RT

2130 3 DEC

PRINTER OCCASIONALLY SPACES ~~UP~~ SEVERAL
LINES INSTEAD OF ONE. THIS EFFECT IS
INTENSIFIED BY PUSHING THE LAMP HOLDER FOR
THE SPACING DISK DOWN LIKE SO:



SRR

left reel of DTA5 scraps

Wick-

2400 3 Dec 66

Found bad +10B margins on 2H (+3V)

Replaced 6205 at 2H19 (bit ~~20~~ 22)

Margin on +10B now $\pm \infty$

0115 4 DEC 66

Ran INSTRUCTION TEST, PART 3 AND IT WORKED
LOADED SYSTEM AND IT SEEMED TO WORK FOR
A MINUTE. THEN IT STOPPED IN A LOOP IN
EXEC MODE INVOLVING THE PI CH-B CODE IN
THE SYSTEM. NO PI'S SEEMED ACTIVE EXCEPT
~~CH~~ POSSIBLY CH 2 WHOSE PI AN PROGRESS
LIGHT IS STUCK ON.

ABOVE BUG WAS MERELY A USER
PROGRAM IN A JDD LOOP → SPR

FIXED DTA5 HUB

0130 @ DEC 66

OUTSTANDING BUGS:

LINE PRINTER EXTRA SPACES - 3 DEC NOTE

ALSO 29 NOV

~~FAN~~ FAN IN BOTTOM OF BAY 2 OF CP 2 DEC NOTE

PI IN PROGRESS ON CH 2 LIGHT ALWAYS ON

TTY 7 CTL KEY 2 DEC NOTE

TTY 2 DOUBLE CHARACTERS 1 DEC NOTE

TTY 1 MAKES BAD SOUNDS AFTER RUNNING

~~FOR A WHILE. CHECK CLUTCH~~

~~ADJUSTMENTS~~

BROKEN

LRR

P.S.

POWER OFF & ON SEEMS TO

WIPE THE RIM LOADER.

TTY 0 OR ~~TO~~ ^{TTY} SCANNER POS #6

SEEMS TO INVENT CHARACTERS SOMETIMES

LRR

P.P.S.

WHAT HAS HAPPENED TO MOD 35?

LRR

DEC 4, 1966 0500 (AM!!!)

ABOUT 1 HOUR AGO THE SYSTEM GOT HUNG UP
ON PI'S AGAIN. BUT THIS TIME I FOUND
WHAT WAS WRONG WITH IT —

~~THE~~ THE PI ENCODER GATE WHOSE OUTPUT IS
PIN R (2N06) WOULD RANDOMLY GO TO GROUND
WITH NO OUTSIDE HELP (ALL INPUTS HELD AT 0V)

THIS WOULD MAKE THE MA RECEIVE PI ENC 33 →
ALONG WITH PI REQ + THE REAL PI CHANNEL REQ

THUS WHEN MA ← PI CH WAS TRUE

BIT 33 WAS GATED INTO THE MA —

WHEN IT WAS OR'D IN AND THE
SYSTEM LOOKED AT IT, IT WOULD STEER
THE SYSTEM TO THE WRONG INTERRUPT ROUT.
AND GET ALL SCREWED UP —

~~WE MIGHT HAVE NOTICED SOONER BUT
THE PI IN PROG. LIGHT ON CHANNEL 2
IS~~

THE CURE WAS AS FOLLOWS: ???

AS I SAID THE ~V GATE IN 2N06R (6124)

WAS AT FAULT AND THERE WAS NO SPARE!

SO I WITH THE HELP OF LIN & JOHN

TRIED TO FIND A 6124 IN THE BRIST



WHICH DIDN'T USE L, M, N, P, R, TO SWAP
WITH AND WE FOUND ONE IN
1R5 (ET 10, FC(B) DSE, FACZE TO ---
I REJUMPERED THE CARDS AND

SWAPPED THEM AND AS OF 30 MIN
AGO THE SYSTEM HAS BEEN RUNNING —

IF AND WHEN WE GET A SPARE
BE SURE AND MAKE THE CLAMPED LOAD
JUMPERS THE SAME — JUST COPY WHAT
I DID AND NOTHING CAN GO

WRONG

RANDY

P.S. THE REASON I DIDN'T TRY AND
FIX CARD, WAS THAT

WHEN I PUT IT IN THE TEST
RACK IT FAIL FOR 1 MIN AND
THEN WORKED FINE!

TRIED HEAT, COLD, SHOCK --- NOTHING —

RANDY


2045 4 DEC 66

FOUND BY PATCHING THAT TTY ϕ IS SENDING
RANDOM CHARACTERS TO COMPUTER. ~~SOMEWHERE~~

SPR

2030 4 DEC 66

A-D converter & multiplexer
CONO BITS



GIVE CONO to 136 Dev 204
 CONO To A-D Dev 429
 CONSO 204
 DATA I 204
 etc.

SPR

1300 DEC 5, 66

LPT SKIPPING LINES ADJUSTED DIODE
LIGHT BLOCK ON SPACING

JPS DEC
+
RANDY

THE A-D IS WORKING; THO NOT FINISHED
IF PEOPLE WILL BEAR WITH ME FOR AWHILE
I, WITH THE HELP OF ARAX, WILL CALIBRATE IT
AND PUT IN THE NEW MOSES TO MAKE IT
WORK TO EVERYONES SATISFACTION.

UNTILL ITS THRU, I HOPE THAT PEOPLE WILL
ASK ME FIRST BEFORE RECONNECTING WIRES
AND REMOVING PROBES + CABLES.

IF I'M NOT HERE PLEASE CALL 368.9050
I HAVE AN ANSWERING SERVICE
RANDY

0305 Dec 8, 66 Power Off Meter 3812.1
C.B.B.

12/9/66
19:10

Recurrent Device Data Error DTAS - changing the scratch tape on DTAS did not cure it.
User error - directory not cleared HJR

12/10/66 - ~~12/10/66~~

14:00 - Repaired bad dly in core 2 which made the power cell logic marginal. EX. AWRQ would not come on during the power on sequence.

- 12/11/66 1. ADJUSTED R/W & SENSE IN CORE 4. SENSE AMP MARGINS ARE -9.5, +10
2. REPLACED SENSE AMP BIT 15 IN CORE 1.
3. ADJUSTED R/W IN CORE 2 SENSE AMP MARGINS ARE -9.5, +10
4. CORE 3 HAS -9.5, +10V SENSE AMP MARGINS.
5. REPLACED INDICATOR DRIVE FOR PI-H #2.
6. REPLACED 1665 CORE 4. MARGINAL BIT 7, PICK UP.
7. FOUND SEVERAL COLD SOLDER JOINTS ON THE 1664 & 1665 BOARDS IN CORE 4. RESOLDERED.

R. BROOK
DEC

2135 11 DEC 66

Printer is giving spurious spaces again.

HJR

12-11-66

TTY 7 gives wrong characters

Weiker

12-12-66 1015

system hung up just after loading computer was cold.

Ch 3 PF

PC = 336

Ch 3-1

IF 1A MCRD MCWR PI CYC EXECMODE
EX 140P EX PI SYNC CLOCK EN CLOCK FLG

Restarting at 140 gives more trouble
but then its OK

Apparently cold computer problems
as Computer was off and room was cold.

ARR

10 15 12 Dec 66

Ran light is intermittent.
Poking it will turn it off & on

ARR

11 20 12 Dec 1966

LPT: is yielding garbage
ES

12/13/66

LPT Spacing problem.
Tightened diode block
JPP DEC.

~~12/13/66~~

2400 13 DEC 66

POWER OFF TEMP = 70°
PLEASE RECORD TEMP ~~ON THE~~ WHEN
POWER IS TURNED ON
ARR

1200

14 DEC 66

Printer was printing garbled
 Found that printer drum was not
 up to speed - drive belt was slipping
 After a while it warmed up and
 worked ok. Probably the
 Drum drive belt needs tightening.

SRR

14 Dec

TTYØ still gives 2 chrs. for the
 price of 1 occasionally

Wisher

2100

14 DEC

TIGHTENED PRINTER DRUM DRIVE BELT
 A LITTLE. PERHAPS IT WON'T GARBLE WHEN
 COLD NOW.

SRR

15 Dec '66 0650

Power Up. Honeywell sez 70°.

All mems came up ok, and system still in core,

J. Sauter

0705 Dec 15 1966

New system died for no obvious reason. Suspect perhaps CP is cold. I will let it cook for a while.

J. Sauter

0800 Dec 15 '66

works ok now. Temp still = 70°

1215 15 Dec 66

~~CP~~ ^{gave} Lisp gives occasional ILL URG
AT user 6p to ~~lisp~~ User 3 time
seems to come and go with CP temp
cold CP = LOSING CP.

SRA

1220

Ran UINS4 to Keep CP warm
and set HONEYWELL TO 74°
JOHNSON TO 72°
TURNED FAN AIR CONDITIONER TO FAN

SRR

TTYØ frequently "prints characters wrong",
ie if you type a "T" sometimes a "Ø" gets
echoed. (The "T" goes in however).

Quam

1235 16 DEC 66

~~Stop~~ ON PARITY SWITCH DOESN'T
WORK. IT ALWAYS STOPS
ARR

1715 16 DEC 66

~~ROE~~

JOHNSON SET TO 70°

HONEYWELL SET TO 74°

ROOM TEMP = 75°

W UNIT ON COOL
E UNIT ON FAN

RESET HONEYWELL TO 73°

ARR

1820 16 DEC 66

MISSING RD RS problems

CPI MC RD
MC WR

F6A

STOP SYNC

MA = 6144

MB = 777,777,777,777

PMA = 026144

PMB = 0

CORE 0

CMA 26 144

CMB = 0

PWR

RD RQ

WR RQ

SYNC

P2 ACT

P2 LAST

SUSPICION: RD RS GOT TO PARITY
BOX, BUT NOT TO CD

TEMP = 73

2030 16 DEC 66 but in core 2

Recurrence of above (different loc. and data).

J. Poole

1600 17 Dec 66 Power off 3983.0 meters
John Halperin

1706 17 Dec 66 Power on 3984.0 J. Poole

1750 17 DEC 66

Missing RD RS Core 2, FGA

LPR

12-17/18:31 Power off 3985.5 D-Steel

12-18/12:15 Power on 3989.6 Purple

12-18/2330 Power off 3996.8 D-Pool

12-19-0900 Power on 3997.0 RB

12-19-66

Printer skips spaces & form feeds as usual

Purple

12-19-66 1235 - - Missing rd. rest - IF 1A
box 3 - twice!

Found that the STOP MODE line is intermittent in the connector at the switch (in the 169). This should be fixed, and it might account for both the "missing read rest" trouble and the occasional malfunctioning of the STOP ON PARITY ERROR switch.

D.P.

12-20-66 0001 Power on 4011.1 J. Sobel

12-20-66

LPT: seems to be skipping random lines and randomly responding to programmed form feeds

I used it to test 2 different tapes with both EDIT2 and PIP2 and trouble was still there

J. Sobel

12-20-66 0107 Power off 4012.1

J. Sobel

12-20-66 0230 Power on 4012.1

J. Sobel

12-20-66 Machine stopped while loading system with EX ILL OP

MC RD

PC = 2

MC WR

IF 1 A

couldn't get system loaded no how

12-20-66 Power off 0318

4012.9

J. Sobel

Dec 20 66

REPLACED BAD 6124 IN IRS
SEE LOG DATE Dec 4 66

READY

Dec 20 66

LPT SKIPPING LINES.
Only on certain places on disk
Pushing down on lamp assy
made problem worse. Put spacer
on set screw which held down
diode & lamp assy. This made
everything OK. Now the lamp
assy can be pushed, pulled, left
right, up, down with no ill
effects
JPS. DEC.

12-20-66

Cards replaced:

1M17 (cold mem. bug)

3E6 (RLA 23)

Core 2, 1E6

Memories all need adjusting - esp. core 2.

12-21-66 0210

CORE TWO HAD A VERY FUNNY BUG —

WHEN WE (DAVE + I) WOULD RUN AUTO BLT OR CHECKS

THEY WOULD RUN FINE. BUT WHEN WE LOADED

THE SYS. IT WOULD GET PARITY ERRORS

IN ONE OF TWO LOC'S IN CORE 2 NAMELY 5576
& 112.

5576 CONTAINED A PUSHJ AND WE FINALLY

FIGURED WHICH BIT WAS BAD (IT WAS BIT 32)

DAVE + I PUT A FEW INST. IN CORE TO R+W

THE SAME BIT PATTERN AND FOUND THAT BIT 32

IN CORE 2 WAS BEING ADDED

AFTER POKING AT IT WE FOUND THAT CMB 32

WAS BEING SET AT WRONG TIME (SHOULD'NT HAVE)
AT ALL

1665 IN 1BC15 P"2" WAS GLITCHING AND

SETTING BIT 32

HAD BROKEN DIODE ON BOARD
RANDY

12-21-66

STOP ON PARITY ERROR SWITCH NOW
WORKS BAD SOLDER JOINT ON PLUG

RANDY

12-21-66 2230

Machine getting lots of
parity errors
A lot of them when reading TV camera
also some when not and not
in my TV buffer

- System died

MEM = 777777

PC = 22

MA = 10

REC MODE

CLK FLG

ld

I.S.

nealy
dead! Couldn't even get the hard wiring
loader in.

12-21-66 Power off \approx 2300 4050.8

I.S.

12-21-66 2350

Cleared core, system runs.
Put mouse back in "RUN" mode. D. P. P.

22 DEC. - 0330

FIXED DATA CHANNEL PARITY
TROUBLE. SOME ~~DATA~~ LEFT A 6102
IN CORE 2, 1D15. REPLACED WITH A 6684.

D. Pool

22 DEC. 1415

Switching memories from MAINT to RUN
(with CP stopped) seems to destroy
core. D. Pool

26 DEC 1615

Line printer sick - start, stop,
manual print. Test Print works OK so
I suspect the controller.

J. Sauter

27 DEC 66

CALL DEC ABOUT PRINTER
will come tomorrow morn.

Randy

12/27/66

LPT Dropping BIT 6

Found - 4V on Pin 5 of I/O Cable at 676 Control unit, however, Pin 5 at the Printer side is dead. Looker now if cable is open, will return Tommorrow morning early to complete this
JPL

DEC.

12/28/66

LPT: Removed 50 Pin I/O cable between LPT and Control, checked cable & connectors, all looked good. Put the all back together & printer works.

JPL
DEC.

12/29/66

FANS HAVE BEEN PUT IN 167 BAY
HOPE THEY COOL!

321-7990 DATAPHONE IS OUT! MA Bell will
PUT PARTS IN MONDAY (IT ATE ONE RELAY)

MON 2

→ LPT IS SICK

DEL HAS WORKED ON IT ALL DAY

WITH NO RESULTS

will come BACK TOMORROW

MADE SOME MODS TO AD-MX

will FINISH ON 30 OF MONTH

Randy

12/31/66 1500

~~DEL~~ CPU has not been turned off since 12/22, and will continue to be left on, following advice from Bob Brooks et al.

TIMER = 4281.8

D. Poole

1/1/67 1300

LPT STILL DOES NOT
WORK

Pugh

1/1/67 1600

There appears to be a bug in the 167--
sometimes it still gives parity errors.

D. P.

1/2/67 2045

Fixed parity bug in data channel by
replacing 6684 in core 2, 1D15 (section 1 was bad)

D. Poole

1/3 working on line PRINTER NO CONCRETE CONCLUSION

1/4 1000

630 seems to have hung while
scanning. console tty still worked but none
of the others. Bottom set of lights not glowing as
normal but brightly lit.

Bill Weiker

1/4 TTY 1 gives 2 for price of 1 and
sometimes wrong characters (random)
TTY 7 still doesn't seem to work!!

Weiker

1800 5 JAN 68

KALLED MA BELL ON DATA SBT
THEY REPLACED IT. IT WORKS.

THERE SEEMS TO BE SOME DISHONESTY

IN THE 630 maybe. some characters
got garbled sometimes maybe. Didn't
have time to investigate. MPR

7 Jan

DIA 2 and 5 spins ^{at random} - Crabs seem to be gone

NAME.EXT=H0L0
NO SUCH FILE
RD\$G

NAME.EXT=HOLO
NO SUCH FILE
RED\$
U RD\$G

NAME.EXT=HFAR

CORE PARITY ERROR, LOCATION 000000122670 OPND = 074071200122
PC = 350000000001 INSTR = 344000000001
DATE = 000635573420 TIME = 212:04

CAM+2/ TRCN OX,0 DP\$G

CORE PARITY ERROR, LOCATION 000000122670 OPND = 074071200122
PC = 350000000001 INSTR = 344000000001
DATE = 000635573421 TIME = 212:34

CAM+3/ 0 DP\$G

CORE PARITY ERROR, LOCATION 000000122670 OPND = 074071200122
PC = 350000000001 INSTR = 344000000001
DATE = 000635573421 TIME = 213:03

CAM+4/ JRST TVP,0

1/2/67 2045

Fixed parity bug in d + channel by

Mr

60

NAME.EXT=HFR
NO SUCH FILE
RDSE
NAME.EXT=HOLD
NO SUCH FILE
RDSE
NAME.EXT=HFR

DATE = 00063273420 TIME = 21:04
PC = 3200000001 INSTR = 3400000001
CORE PARITY ERROR, LOCATION 0000000000

CAM+24 TRON OX.0 DPSE

DATE = 00063273421 TIME = 21:34
PC = 3200000001 INSTR = 3400000001
CORE PARITY ERROR, LOCATION 0000000000

CAM+34 B. 0750

DATE = 00063273421 TIME = 21:34
PC = 3200000001 INSTR = 3400000001
CORE PARITY ERROR, LOCATION 0000000000

CAM+34 TRON OX.0 DPSE

in the log major & some characters
got garbled sometimes maybe. Didn't
have time to investigate. HFR

7 Jan

DTA 2 and 5 spins ^{at random} - brake seems to be gone

Pinglo

7 Jan.

Auto sensitivity on TV camera does not work

Pinglo

9-Jan-67

Parity errors. two at 33315, one at 53747, one at 54025.

J. Sauter

10 Jan-67

Printer up & running.

Replaced Lamp Assembly on Code wheel
Replaced Diode cover on code wheel
Replaced Diode in disc Line Count Assembly.

JSS D.E.C.

10:30 AM 1-11-67

fast memory went non-ex, killing
the system. Restart (DANNIT) turned
off STOP and the system could then
be reloaded.

J. Sauter

1350 1-11-67

REPLACED 4604 CARD @ 1A7 IN 136 -

NARROW RESET PULSES TO CHAR COUNTER (1A16) -

DECTAPE TEST CAUGHT AT -

2020 11 JAN 67

Parity error

CORE PARITY ERROR, LOCATION 00000072515 OPND = 777773052521
PC = 750000022654 INSTR = 231040000044
PI STATUS = 000000120037 TIME = 216:35

SJR

2025 11 JAN 67

CORE PARITY ERROR, LOCATION 000000072515 OPND = 77773052521
PC = 750000021765 INSTR = 342040002032
PI STATUS = 000000120037 TIME = 223::03

CORE PARITY ERROR, LOCATION 000000072515 OPND = 77773052521
PC = 750000022002 INSTR = 554107000000
PI STATUS = 000000120037 TIME = 239:14

CORE PARITY ERROR, LOCATION 000000071355 OPND = 77773051401
PC = 750000022654 INSTR = 231040000044
PI STATUS = 000000120027 TIME = 2251:36

0830 - 1/12/67

Log Out's ON CTR WHEN I CAME IN -

OVER

0830 1/12/67

Log Outs ON CTY WHEN I CAME IN
Ron

↓
↓
CORE PARITY ERROR, LOCATION 000000075105 OPND = 061762045104
PC = 750000032654 INSTR = 231040000044
PI STATUS = 000000120027 TIME = 327::24

↓
↓
CORE PARITY ERROR, LOCATION 000000075005 OPND = 007730106102
PC = 750000032654 INSTR = 231040000044
PI STATUS = 000000120037 TIME = 515:10

1120 12 JAN 67

TTY LINE PATCH 2 DOES NOT
RECEIVE CHARACTERS FROM THE
TELETYPE KEYBOARD CORRECTLY

JRR

1340 Jan 13

TV camera getting parity errors
(PAR ERR light on-167).

J. Sauter
(happens even when no one is using the camera!)

(EXAMINE 52515)
IOL MEM REF FROM 5365

↑C

.C
2K CORE LEFT

.CORE 14
2K CORE LEFT

.CORE 0

.CORE 14

.R LISPXY 14

ALLOC↑↑C

.K

.?

.?

.

CORE PARITY ERROR, LOCATION 000000072515 OPND = 777773052521

PC = 750000022654 INSTR = 231040000044

PI STATUS = 000000120037 TIME = 13:27

CORE PARITY ERROR, LOCATION 000000072505 OPND = 777773047621

PC = 750000022654 INSTR = 231040000044

PI STATUS = 000000120037 TIME = 14:09

CORE PARITY ERROR, LOCATION 000000072515 OPND = 777773052521

PC = 750000022654 INSTR = 231040000044

PI STATUS = 000000120027 TIME = 25::47

CORE PARITY ERROR, LOCATION 000000072515 OPND = 777773052521
PC = 750000021765 INSTR = 3420400022032
PI STATUS = 000000120027 TIME = 2322::12

?

399693

.C
OK CORE LEFT

.DAY
11-JAN-67
2326:32.03

CORE PARITY ERROR, LOCATION 000000072515 OPND = 777773052521
PC = 750000021765 INSTR = 3420400022032
PI STATUS = 000000120037 TIME = 2328::19

C
?
.C
14K CORE LEFT

.R LISPLY 12
JOB 2 INITIALIZED
STANFORD 2.6/11A
11-JAN-67
2330:1.52

ALLOC?

1/13

7747

loses characters

Quam

THE CLOCK:

~~A wonderful~~

A wonderful new device has been added to the computer. It is a clock. It is device 43 ϕ . It is read with a ~~DATAI~~ DATAI. It gives you 36 wonderful bits. They are:

bit

ϕ

Clock Invalid

1

Year Invalid

8-11

high order digit of year ($\phi-9$)

12-15

low order digit of year ($\phi-9$)

16-19

Month ($4_{10}-15_{10}$)

20-24

Day ~~4~~ ($1_{10}-31_{10}$)

25-29

Hour ($8_{10}-31_{10}$)

30-36

Minute ($4_{10}-63_{10}$)

P. Pett

1-15-67 1645

PC change enable came on for no obvious reason. A dip lead from 2M2WT to ground. System died. Reloaded from tape.

J. Sauter

DEFPROP NOW (LAMBDA (LIST) (LISTAPPEND (QUOTE L(LIST)) LIST
(↑C

.K

CORE PARITY ERROR, LOCATION 000000036601 OPND = 757072107600
PC = 350000104274 INSTR = 200040064420
PI STATUS = 000000120037 TIME = 224::31

15 JAN 67

?

2330 15 JAN 67

PARITY ERRORS ~~THE~~ FROM SYSTEM IN CORE 1

BLT complained about dropped right
 $\frac{1}{2}$ of various locations. Pounded
on back of 1664's & 1665's in CORE 1

~~Bob~~ Bob went away.

left BLT grinning

SRK

8:40 16 Jan

Core Box 1 would not (read write?)
data in any location whose address had
bit 31 on. Was still checking effect when
bug suddenly disappeared

Wether

10:30 AM 16 Jan.

System suddenly started getting parity errors
(next page). Pounded on bedsheet boards in core 1.
no help. Loaded BLT. worked fine in non-interleave. Loaded
system. Worked fine. Loaded system in interleave. worked fine.
Bug Went Away!

J. Santos

55K CORE LEFT

.C 33

.K

[somebody typed in the time wrong!]
J.S.

CORE PARITY ERROR, LOCATION 000000164061 OPND = 000012002000
PC = 750000000000 INSTR = 504154640000
PI STATUS = 000000120027 TIME = 133:45

CORE PARITY ERROR, LOCATION 000000164065 OPND = 000010000000
PC = 750000000000 INSTR = 504154640000
PI STATUS = 000000120027 TIME = 134:04

CORE PARITY ERROR, LOCATION 000000164071 OPND = 000370200200
PC = 750000000000 INSTR = 504154640000
PI STATUS = 000000120027 TIME = 134:24

CORE PARITY ERROR, LOCATION 000000164121 OPND = 000000000000
PC = 750000000000 INSTR = 504154640000
PI STATUS = 000000120027 TIME = 134:43

CORE PARITY ERROR, LOCATION 000000164135 OPND = 000010000000
PC = 750000000000 INSTR = 504154640000
PI STATUS = 000000120027 TIME = 135:03

CORE PARITY ERROR, LOCATION 000000164161 OPND = 000000000000
PC

system died here

FORM 811-B Moore B smess 10/15/65

1-16-67 noon

Some of the TTY's feel bad.

In particular:

TTY1 needs the position of the first character on a line adjusted.

TTY7 sends wrong characters occasionally.

TTY4 likewise.

J. Sauter

1-16-67 12:30

System died, wouldn't restart or reload.

Switches showed that core 1 was dropping bits.

Put memories in normal and loaded B.T.

It started complaining right away. Will call DEC at B.O.O.

J. Sauter

1/16/67 -

CORE 1 PARITY BUG -

UNSOLDERED JOINT (PIN 7) of 6227 BOARD @
LD23 - APPEARS OK NOW - BLT RAN FOR \approx
5 MIN ERROR FREE -

1/16/67 -

DATA CHANNEL DROPPING BITS
AGAIN: A WORD OF MAX INTENSITY
SHOULD READ 6 --- 6, INSTEAD
COMES OUT 622662266266.
TROUBLE TRACEABLE BACK AS FAR AS 167
SHIFT REG. SHIFT PULSES LOOK ODD
(27-35 AT LEAST). NO TIME TO
CHASE NOW.

W 19 W

1/17 - DATA CHANNEL TROUBLE FIXED -
OLD WIDED TERMINATOR GOT SHIPPED
INTO GUTS OF KLUJE.

W

1-19-67

TTY #1 HAS BEEN FIXED (I THINK)

RANDY

1/21/67 22:10

TTY's still feel bad, as follows:

TTY 2 gives multiple chars + key stick

TTY 1 prints while carriage is returning

TTY 4 transmits wrong chars

TTY 0 also (maybe receiver)

J. Sauter

1130 21 JAN 67

Oiled TTY 2, adjusted keyboard
no sign of key sticking.

JRS

0243 22 JAN 67

Oiled and adjusted carriage return
dashpot and keyboard on TTY 1

JRS

1/22

1:30

TTY 2 gave a double character

marker

1/22

2300

22 Jan 67

Plotter connection rewired:
changed

1) 2 WATT RESISTORS ARE NOW
USED WHERE 1/2 W RESISTORS WERE
DISSIPATING 1 W

2) Codes to plotter are changed
to match MAYNARD

CODES NOW ARE

1	RIGHT	PEN
2	LEFT	PEN
4	TOWARDS	TOP OF DRUM
10	AWAY	" "
20	DOWN	PEN
40	UP	PEN

APR

0100

23

JAN 67

FAR GREEN MONSTER AIR
CONDITIONER GAVE HOT MOTOR
SMELLS. TURNED IT OFF.

APR

0105

23

JAN 67

TROUBLE WAS NOT AIR COND
IT WAS THE PRINTER! JRE

226-1300
DEC 29 0400
30

0110 23 JAN 67

MULTIPLE OUTPUT P. S. WAS
VERY HOT IN TRANSISTOR TRANSFORMER
AND BOTTOM HEAT SINKS

ARR

1/23/67 0845

BUGGED DEC ON LPT - WILL HAVE
SOMEBODY 4PT THIS MORNING -
Ran

0530 23 JAN 67

AL ROBERTS OF DEC CHECKED PRINTER.
FOUND "MULTIPLE OUTPUT POWER SUPPLY"
WAS RUNNING VERY HOT, BUT PRODUCING
CORRECT VOLTAGES. HE SAID HE WILL ORDER
A NEW ONE FROM MAYNARD. HE
ALSO SUGGESTS THAT WE KEEP USING
THE PRINTER, BUT TURN IT OFF WHEN
NOT IN USE.

ARRussell

1000 23 Jan 67

Adjusted TTY2 Keyboard
ARR

1/24/67

Ran Dec tape test on all bad DEC tapes -
All but 2 are now ok - Ron

CRITY ERROR, LOCATION 000000070515 OPND = 007723050516
000002654 INSTR = 231040000044
00000120027 TIME = 242:01

Jan. 25-67

GOD DAMN

TTY2 gives

DOUBLE CHARACTERS !

- P. R. A.

26 JAN. - 0025

12-BIT DAC BENEDICTUS EST.

ERROR $< \frac{1}{4}$ L.S.B.

ALSO, DAC WILL RETAIN ITS FINAL SETTING AT END OF A TRANSMISSION.

D.W.P.

0940 26 Jan 6

TTY ϕ sends or prints spurious
Tried patching ~~to a def~~ LINE PATCH
to a different TTY and ~~it~~ cleared the
trouble. TTY ϕ probably has dirty
contacts.

APR.

1100 26 JAN 6

CORE MARGIN

CORE 0	CORE 1	CORE 2	CORE 3
SAS +10 -8 +10B	SAS $\pm 10V$	SAS $\pm 10V$	
DRIVERS & SELECTORS ± 10	10V (MS) $\pm 10V$	$\pm 10V$	

AUTO BLT RUN 4 MIN

OKAY

RANDY

27 Jan 5:20

The delay in the PTP control for the Calcump has been tweaked (Tweak tweak). The total cycle time is now about 3.4 ms. (i.e. abt. 300 chr/sec.).

The tweak involved moving a jumper on the 4343 & the prints have been modified accordingly.

P. P. P.

28 Jan

TTY7 gives incorrect characters @ for A R for S sound like losing low order bit

Weller

2135 28 JAN 67

SYSTEM GOT MANY PARITY ERRORS AT LOCATION INDETERMINATE.

RAW BLT OK for 6 min then
PE @ 69061 WD = 76216302216C
SAME WD IN CORE 1, MB BLT sup err in BIT 15 m
~~SAME SAME~~

~~Had to recheck up bit 15~~ WAS DROPPING BIT 15

ANOTHER ^{PAPER} PAPER

LOC 41001 C = 7654 02 025 001

LOC 41011 C = 7654 12 025 011

LOC 41021 C = 7654 22 025 021

LOC 41061 C = 7654 62 025 161

POUNDED ON IB of core 1
TO GET DROPPED BIT 9

~~HIT~~ BEAT ON IB SOME
MORE. NOTHING

HIT CANNON PLUGS ON LB
STOPPED

LOWEST CANNON PLUG ON IB IN C₀
IS VERY SENSITIVE -

FOUND BROKEN WIRE ON PIN 3
OF SAID CANNON PLUG. CMA BIT 30
ZERO SIDE.

RESOLDERED.

BLT RUNS OK

FOUND A SIMILAR BUG IN TOP
CANNON PLUG OF CORE ϕ DOESN'T
SEEM TO INTERFERE WITH NORMAL OPERATION
SO I DIDN'T PURSUE.

APR

0100 29 JAN 67

ALSO WIGGLING CABLE TO MIDDLE
CANNON CONNECTOR IN ~~BOX~~ CORE 1
CAUSES PARITY ERRORS.

SRP

1000 - 30 JAN -

LPT SCK - WON'T COME OUT OF ALARM
STATUS WHEN POWERING UP -
10:15 - CALLED DEC -

10:45 checked Printer, Found by hitting
IT could cause Alarm. in TurboK
on side door open. I don't know
if this is the major problem -

we'll see

JSD DEC

1400 31 JAN 67

POWER CONSUMPTION WITH COMPUTER

& TTY'S, DEC type 30 display

BUT NO PRINTER 28A, 44A, & 50A

SRP

31 Jan 67

1600

Analex Printer:

~~The~~ Analox arrived To check Printer and install "MULTI-PURPOSE" Power supply, if Necessary.

Found following problems:

Power input Line on TB 301¹ and Terminal Block were badly burned, resulting in stretch Noted on 23 Jan 67.

~~The~~ Cleared up wiring & moved to TB 301-2 (Unused). checked Current on Multi-purpose Power Supply.

input AC	Running 4.4Amps	STATIC 4Amps
-18V	8.8 Amps	8.0 Amps
+6V	4 Amps	3.9 Amps
-6V	2.1 Amps	2 Amps

Concluded at this Time that Power supply, although hot looks O.K.

Problem was Most Probably Poor connection on Terminal Block.

J.P. Smith
D.E.C.

31 Jan 67

2015

TTY 2

still gins 2

chrs for price

561.

Weber

1 Feb. 1416

Line Printer, when given 15, 177, 21

occasionally prints the last 2 characters = .
see attached output

Print

2 Feb

IT HAS FOR
PART OF
ONE
Member

NEW VERSION OF COMPLR
WILL NOT WRITE EOF
YOU MUST DO (OUTCLMT)

2000 3 FEB 67

TV CAMERA SUFFERED FROM A
SUDDEN LOSS OF SENSITIVITY. NO CLUE
AS TO WHY. THE AUTO SENS
ADJUSTMENT IS NOW OFF.

JPRussell

6 Feb -

CORE BUGS - CORE 1

INTERMITTENT { J1B27F 1 → 14 BITS 22-28 @ A1 BUFFERED → TO P1B27M R, W+Y
J1B28F 1 → 14 BITS 24-30 @ A1 " → TO P1B28M R, W-X SEC
J1B26F P2M 11 (B273) INTERMITTENT
1 BC11 K (B275) BROKEN WIRE -

CORE 1 NOW OPERATES, BUT WILL DROP BITS INTERMITTENTLY IF CONNECTOR 1B26F IS POOR AT -

RAB -

6 FEB 1745

MQ35 NO SHLT; REPLACED 6205 IN 2HV24.

J.P.

Evidently TT42 gives 2 chrs for the price of one ACH.

8 Feb 67 14:00

Core Problems.

Core ϕ

- J1B26m Cold Solder joints BIT 7
Resoldered all joints & coated pins with
Mercury.
- J1B27m Bad Connection, Pin 4. Resoldered
& coated pins with Mercury.
- J1B28m Bad Connections. Resoldered all
connections on Front Plug.

Core 2

- J1B26m Intermittent dropping BIT 2 & 3.
Resoldered Connections.

JPL
DEC.

10 Feb 67 5:10

The T.V. Camera quit working again.
Same bug. I got out the scope & verified
that the problem is in the Video assembly
Card (Not to be confused with the preamp). The
confirmation being that fine high quality
video goes in but doesn't come out. A binary
search got me as far as proving that the

problem is in the first half of the circuit (i.e. before Q4).

The fix for the problem when it happens is to turn off the camera. Put the extend card on the video card. Get out the scope. Turn the camera on. Put it & the scope warm up. A red start to trace the bug. The bug will immediately disappear. If you wish the bug to remain gone, leave the scope probes in the camera. In this case the bug will only appear when you are on the other side of the room & will leave as soon as you approach.

P. P. To

2-16-67

10:00

Clock read June 10

2-10-67

TTT
DWB

LETTERS

TEACHERS

Weekly

9 Feb 67

BAD R401 IC 17 (A-D) CLOCK-

~~Reset~~ ^{Set} Clock 3 to 6Kc using 401 cond out of IC 16
(clock 2) Pm

2/10/67 CAMERA LIVES - TROUBLE

WAS $C_{\infty} \leftarrow C_{\infty} // 1000 \Omega$

IN POSITION C29 OF VIDEO CARD.

THIS CAUSED BLANK LEVEL TO RISE
TO ABOUT +5V, CUTTING OFF QB.

WTH

1815 10 FEB 67

VIDEO HAS BEEN RE-BLESSED ON REMOTE

APR

10:00 11 Feb 67

Several parity errors occurred in
core while reading & processing

T.V. camera

P. P. P.

MEM AT USER 1

.?
ERRN JOB 0
NON EX MEM AT USER 1
↑C

CORE PARITY ERROR, LOCATION 000000117513 OPND = 000002644000
PC = 550000063546 INSTR = 201540000006
PI STATUS = 000000120027 TIME = 843:45

CORE PARITY ERROR, LOCATION 000000106323 OPND = 000002242002
PC = 550000063546 INSTR = 201540000006
PI STATUS = 000000120027 TIME = 845:34

CORE PARITY ERROR, LOCATION 000000115017 OPND = 400040400000
PC = 550000063546 INSTR = 201540000006
PI STATUS = 000000120027 TIME = 848:08

CORE PARITY ERROR, LOCATION 000000116733 OPND = 000000444004
PC = 550000063546 INSTR = 201540000006
PI STATUS = 000000120027 TIME = 849:17

1230 11 FEB 69

LINE PATCH 2 ON 630

GIVES GARBLED CHAR ON INPUT,

12 Feb 2:25

APR

TTT YY 2 2
GGTTVVVEEES
CC HARRSS

ESTTILL

DOOOUBBLEE

Wink

12-Feb-67 10:30

TTY6 has a bad shift key. It will not shift for certain characters (c.f. -/=, N/r) but will for others (c.f. :/*)

P. P. P.

13-Feb-67 4:10

To keep from having the machine go down during the day, we installed the IO bus connections + power jumpers to the MTAPE CONTROL but did not turn the drive on.

P. P. P.

13 Feb. 1967

Completed Preventive maint on
following model 33 teletypes

Ser. # 53385 replaced 2 gears

33939

34467

37780

52515

34466

30996

53384

replaced 2 gears and 1 platen

replaced platen

Jesse Gonzalez

Feb. 14, 1967

22:00

Magtape had 2 bugs:

1. The system would hang in a constant channel 5 break during a backspace.
2. The system would get totally screwed if you asked it to read (the MTape) a record shorter than it really was.

I discovered that there was no wire to pin U of 3D2 (see Motion Delay print, coordinates C7, level MD IRC)

Clip-leading this pin to pin P of 3D25 (see same print A8) cured both bugs.

P. P. J.

P.S. I made the jumper incarnate in teflon wire.

P. P. J.

15-Feb-

Reloaded System - 0830

Run

16 FEB -

TTY5 OCCASSIONALLY PRINTS "+" FOR "9"
R

16 Feb

TTY2 GIVES
DOUBLE
CHARACTERS

STILL!!!

over

TTY 5

NO CASE SHITS!

18 Feb

Finally got tired of waiting for someone to fix tty 2. Interchanged TTY2 and TTY4

Wuher

19 Feb

TTY 1 seems to like to give lots of periods after RC.

② ~~Here~~ Verts Hold on TV monitor is bad

Purple

1058

20 FEB 67

Found TV Camera on AFC or PUT IT ON FC AND IT SUNK without HUNTING, Master Osc. is deliberately put out of adjustment so that the beats with

the computer clock interrupts
are ~~rapid~~. Frequent.
APR

20 Feb

TTY 2 needs a new ribbon

Pinb

1800
21 FEB 67

AUDIO INPUT MULTIPLEXER UNIT GOT A
RESISTANCE TO GROUND WHEN SELECTED.
TRADED A101 with CH 14_g & 15_g
WHICH I ~~FOR~~ I HOPE AREN'T USED.

1DD
.22 FEB.

CORE PARITY ERROR, LOCATION 000000053747 OPND = 000000033746
PC = 750000021775 INSTR = 202101000000
PI STATUS = 000000120137 TIME = 232:14

#750 22 Feb

Analex printer hangs up trying
to print after first word or so
printed

SRP

22 Feb.

Repaired printer (teletype) # 1 + 4
Double tripping keyboard # 4 NC.
2 hrs on # 1 tested by Bill and O.K.
Gonzales

2330 22 FEB

Printer trouble was intermittent
4301 delay in DEC printer controller A13
It was sensitive to twisting. Resoldered
some suspicious joints on the module.
Printer works

SRP

23 Feb

Rock think it's June 23
Weiber

23 Feb

See TTY2 NOT

WORK - SEE, SEE, SEE,
LOOK, LOOK, LOOK
LOOK AND SEE.
SEE TTY2 LOSE.

Wurber

```

00100  TITLE SETBTS
00200  IN\ENTRY SETBTS
00300  ;COMMENT CALLED WITH\AS CALL SETB:
;COMMENT CALLED AS  CALL SETBTS (TO,SZ,RHB,
00400  ;WILL TAKE THE RIGHT-HAND MOST SZ BI
00500  ;THEM IN TO SO THAT THE RIGHT-MOST
00600  ;BIT RHB. ALL OTHER BITS ARE UNCHAP
-> 0 0700  ;FROM LEFT TO RIGHT
00800
-> 00900  SETBTS: HRR 0,(16)      ;GET ADDR
0 1000

*I.
00900  SETBTS: 0
01000  HRR 0,(16)      ;GET ADDR
0 1100  LDB 0,BP1      ;SET SIZ
01200  EXCH 17,02(16) ;GET POSI
01300  SUBI 17,0D35    ;GET INTO
01400  MOVNS 17

```

25 Feb 67
TTY4

gives double characters

RR

26-FEB-67 2250

Mag tape sometimes thinks a tape with a write ring is in write lock. Kicking it after helps, if that doesn't demount the tape and mount it again, FORCEFULLY.

J. Sauter

27-FEB-67 0242:09

PARITY ERROR 72515. bit 15 was dropped (it was a Lisp atom).

0400 27 Feb 67

~~title~~ CONSOLE ~~FE~~ TTY P/A
BITS OCCASIONALLY CLEARED OR SET TO
1 instead of 5
JRS

1-MAR-67 1320:03

PARITY ERROR 70045. Suspect Bit 15 again.

J. Sauter

1-MAR-67 2000

clock says Sept + year invalid

J. Sauter

3-MAR-67 0140

System died in CHS. When reloaded
got a "PARITY ERROR -- LOCATION
INDETERMINATE".

J. Sauter

3-Mar-67 9:00

TTY 0

GARBLES

CHARACTERS

3-3-67 B. Leonard

TTY2 adjusted left hand margin

TTY 4 Return adjusted f Double
Keyboard Tripping

J. Gouyales
TTY Repairman

~~3-5-67~~

line patch 2 ?

3-5-67

DTA 5 has coasty
trouble

Winter

3-5-67-2350

TTY 2 INVENTS, GARBLES,
AND DROPS CHARACTERS (ON INPUT).

D. Pool

3-6-67 0500

I agree. J. Sauter

TTY1 multiple characters

J. A.

3/7/67 "TOP OF FORM" button on front on
line printer stuck in "up" position.
Back button works.

Lawrence

TTY ϕ prints characters on top
of one another

Ken Siler

0859 8 Mar 67

Top of Form button works for me, now

SRR

0920 8 Mar 67

tested dectapes

delays as timed by program are

38.6 MS
183 MS
308 MS

OK

adjusted start & stop delays on all dectape
drives. according to manual

SRR.

1150 8 Mar 67

LPT is giving spurious spaces.
about 1 per page

RRR

1130 9 Mar 67

TTY 4 has trouble typing "S" and "T"
together

Purple

1130 4 MAR 67

TTY 2 HAS BEEN CLEANED-UP (DISTRIBUTOR)
AND SEEMS TO BE FINE NOW

Randy

TTY 4 HAD BEEN WIRED WRONG
WORKS NOW Randy

1200 10 Mar

DTA 2 slips

Purple

1400 10 MAR

LPT NOW HAS MOD # LIGHT SOURCE
#222 PRE FOCUS LAMP + 3V BATTERY
BATT. WAS OLD SO WHEN ITS
GONE USE THE LITTLE BICO SUPPLY.
LIGHT SOURCE SEEMS BETTER, LESS RUGGY
BUT LESTER WANTS DEC TO FIX IT
SO ITS IN LIMBO NOW
SORT OF WORKS

Randy

1150


MAR ~~80~~

IOTS TO Devices numbered 700
or above are now legal in user
mode. See drawing EX.

Clock is now device 730

CONI to 730 gets microsecond
and second count

DATAE gets slower part as before.



R. R. T.

1545

Kept getting device upset even from DTA3.
Tape read correctly on any other drive

Rad

CORE PARITY ERROR, LOCATION 000000022020 OPND = 174771204034
PC = 750000021602 INSTR = 200040000015
PI STATUS = 000000120027 TIME = 1422:12

try & wait print to right

CORE PARITY ERROR, LOCATION 000000022010 OPND = 175477204035
PC = 750000020743 INSTR = 202000001121
PI STATUS = 000000120027 TIME = 1422:30

FRIDAY 10 MARCH 67

*replaced R line code LINDO 1000
POWER UP ALP.*

16 MARCH

TTY \emptyset FAILS TO PRINT SOME LETTERS SOMETIMES,
G, S, A, N NOTICED.

Ben Radman

1150

MAR 80

IOTS TO Devices numbered 700
or above are now legal in non

mode, See drawing FV

Clock is now 7:30

CONF # 770 get processed

and send

DATA = [unclear]

R. R. [unclear]

1945

Kept getting device input even from DTA3.

Tape read correctly on any other device

Page

13 MAR

TTY ϕ want print /s ... right
----- prints /T....
also gives double characters —

M. Kahn

13 MAR

REPLACED LINE CODE LAMP ASSY
PRINTER UP ALR.

16 MARCH

TTY ϕ FAILS TO PRINT SOME LETTERS SOMETIMES,
G, S, A, N NOTICED.

Bernie Buchanan

17 MARCH 67 11:30 AM

TAPE READER BLEW A FUSE ON ITS BACK PANEL
AND SMELLED BAD, SHUT DOWN AT 10:15 -
BACK UP AT 11:20

SEEMS THAT ONE OF THE LINE FILTERS SHORTED
OUT, GOT HOT, AND STARTED TO LEAK OIL ALL OVER
BY PASSED FILTERS AND CLEANED UP UNIT
WILL REPLACE AS SOON AS IN STOCK

PULSED DEC; OF THE FACT THAT WE
HAVE NO MAINT. BOOK ON THE READER

Roady

1340 17 Mar 67

Printer trapped 10A "Printer"
breaker. Reset it. It work OK

RRussell

2400 19 Mar 67

Reset tension on printer ribbon to max.
in the hope of getting ribbon to last longer.
Time will tell.

RRussell

~~1720~~

~~20 MAR~~

~~(ZERO 0.0)~~

5:40 21-mar-67

The ribbon on the printer stopped altogether several times & had to be started with the cranks.

LOSE LOSE LOSE

P.P.S.

0915 21 MAR 67

PRINTER WON'T COME UP.

DRIVE MOTOR WON'T TURN DRUM ETC.

TRIPS ITS BREAKER AFTER A FEW SEC.

S.R. Russell

21 MAR 67

TTY1 NOT FAITHFUL. R

22 Mar - 10 AM

Mag tape errors - can't read records written in DR mode except for the first few.

Ray Reddy

MARCH 22 67

TTY 1 HAS BEEN CLEANED UP (DISTRIBUTOR & KEYBOARD CONTACTS) AND OILED
SEEM OKAY NOW

Randy

MARCH 23 67 0845

Ran TS MAIN FOR 30 MIN:

ALL SEEMED OKAY

+ AUTO BLT 1030 WHILE NO ONE WAS
ON FOR 30 MIN:

IT TOO RAN FINE

Randy

MARCH 27 67 09:00 - 1000

MICRO CHECK: SA MARGINS	0	1	2	3
	-9	-8.5	-9.5	-9
DRIVER, SELECTIONS, TIMING	±10	±10	±10	±10
AUTO BLT: 30 MIN RAN FINE	±10	±10	±10	±10

HIGH SPEED MEM CHECK: OK OK OK OK - NO ERRORS

MICRO CHECK: BED SHEET'S MARGINS -5 +2.5 - - - - -
-15

6684'S -3+7 -3+7 -3+7 -3+7



IN RUNNING THE MARGINS

WE FOUND THAT ALL CORE MODULES ARE

LOW ON $+ \leftarrow -15$ AND $- \leftarrow +10$

ON THE FOLLOWING:

IF YOU MARGIN THE BED SHEET BOARDS

YOU GET GOOD MARGINS BUT ON -15

IT WILL FAIL AT ABOUT $-12V$ ON ALL OF CORE

IF YOU MARG. THE 6684'S $+10$ ON THE SWITCH

IN EACH CORE BOX YOU GET $-3 \leftrightarrow +7$

SEEMS LOW BUT THEY SEEM TO WORK.

ALL ARE THE SAME

Randy

1425 27 Mar 69

Many Parity errors in core 3
cleared core 3 & it went away.

ARR

3/28/67 2115

Five patch 2 garbles characters
on input.

J. Sauter

29 Mar 67 2300

MUCH TROUBLE WITH CORE ZERO.

PIN 27 OF 1L16 (ON BACK OF MEM STACK)

IS EXTREMELY MARGINAL. THERE ARE ALSO

TROUBLES WITH DROPPED LEFT RT 1/2 WD WHEN

BITS 29 30 +31 of address are all zero.

CHANGED 1664's with core 4 and

de-interleaved. 167 & TV camera won't
work.

ARR & JRB.

30 Mar 67 1400

Found broken wire on pin K of 1L16.

Resoldered and right half of words came back.

P. P. P.

30 MARCH 67

1. Broken above wire with current prob

30 MAR 67 - R

SEE "MANUAL PRINT" LIGHT & TAPE "PH/EEP" LIGHT

ARE THESE BULBS OF DIFFERENT VOLTAGE RATINGS? IF YES, WHY? IF NO, WHY ARE THEY OF VARYING BRIGHTNESS?

3-30-67

I THINK THEY ARE IN SERIES? R

Randy 3/31/67.

A Scorpion has been connected up beside the DEC scope. The three push buttons may be read in with the spacewar buttons. They set bits 24, 25 and 26 when pushed.

The three joints are connected to the multiplexer and AD as follows:

shoulder	channel 22
elbow	channel 23
wrist	channel 24

IT WORKS - - - - - Lou Paul.

3-31-67 1100

PARITY ERROR LOC 24074

CHECKED THE BOX'S, BUS ETC. Randy

BUT TROUBLE WENT AWAY BEFORE

I FOUND ANYTHING

Randy

2245 3-31-67

Box \emptyset giving several parity errors at 24074.

J. Sauter

4-2-67 15:15

Ran Autoblet to try to fix parity (box \emptyset) problem. Bit 19 kept being in error (on & shouldn't be). I considered it likely that the error was in the inhibit driver (since the bit was on). Magic address analysis indicated it was the section driving quad 2. Anyway the appropriate driver is 2K6. I exchanged it with 2K5 (bit 18). The "bit in error" immediately changed to 16. I replaced the module (a 1998) and the parity errors & bit goings went away.

P. P. J.

4-3-67 0230 AM

SEVERAL CORE PARITY ERRORS

LOC INDETERM:

Randy

4-3-67 930 AM

The following have been noted thus far this morning

- 1) TTY2 when you give edit 2 a CR sometimes the teletype only echos a line feed and the next line has all the characters typed on top of each other (see sample)
- 2) The following DEctapes need brake adjustments
DTAY, DTA1 ✓
- 3) DTA1 slips badly ✓

Purple

4-3-67 1800 DTA 1-8 HAVE BEEN

CHECKED AND THE STOP TIMES ADJUSTED

ALL RESPONDED EXCEPT DTA-8, THE

LGSA POT SEEMED OUT OF RANGE.

IF TROUBLE IS HAD

THE UNITS WILL HAVE TO BE TAKEN

OUT FOR A CHECK

Randy

~~3/24~~ APR 3 '67 1322

Paper tape punch tends
to tear paper tape.

J. Sauter

4/3/67 TURRET MOTOR BLEW $\frac{1}{10}$ A FUSE.
NOW HAS $\frac{1}{4}$ A FUSE - WE OUGHT TO
GET & INSTALL THE RIGHT ONE -
FUSE LIVES NEXT TO TURRET
ON RIGHT SIDE.

WTM

4/3/67 PUNCH HAS BEEN FIXED —
SOMEONE FAILED TO EMPTY IT AND
THE ~~CHUTE~~ AND ~~PUNCH~~ BLOCKS WERE
JAMMED

Randy

4/3/67 PEOPLE HAVE BEEN COMPLAINING ABOUT
LOOSE REELS ON THE DECTAPE UNITS.
I MEASURED THE HUB AND SOME REELS
WITH A CALIPERS AND FOUND THE HUB
IS SET AT A ~~OFF~~ REASONABLE TENSION
BUT IF I SET IT WIDER, 75% OF THE
REELS WON'T COME OFF →

SO IT STAYS THE WAY IT IS
IF YOU HAVE LOOSE REELS SEE
ME FOR A REPLACEMENT OR CHECK

P.S. BRING IT TO MY ATTN:
BEFORE OR AFTER YOU USE IT.
OKAY

RANDY

4-4-67 7:00

The machine will not run the loader :

```
.R LOADER 30  
*/DDTA2:BIN?  
ERROR IN JOB 1  
ILL MEM REF AT USER 1222  
!C
```

..

The result is the same regardless of
tape drive wrap is on, system loaded (2.8/05C or 2.8/03B),
Job num, etc. Appears to be hardware problem.

I deinterleaved and things run fine. If
re interleaved & same problem. I deinterleave & it
runs fine so I leave deinterleaved. P. Pet

4-5-67 9:00

Many parity errors. Pan alt,
* problem in bit 25. Interchanged
LH7 with LH8 in core ϕ (sense amps),
Problem went away.

P. P. J.

4-4-67 Bug on 4-5-67 9:00

→ CORE (1) WAS IN LOOSE MODE

RH + LH'S WERE BEING DROPPED

+ SOME LOC'S WERE LOSING RANDOM BITS

+ CORE (0) LOC 14000 WAS PICKING UP AND
DROPPING BIT 25.

CORE "1" Bug

① THE BALUN BOARDS SEEMED TOUCHY TO
VIBRATIONS SO THEY WERE REMOVED
AND ALL PINS WERE CLEANED + SOCKETS WERE
WIRED OUT.
THIS SEEMED TO STOP HALF WORD ERRORS

② IT WAS NOTED THAT LOC'S IN CORE Y'
WITH BIT 31 U) WERE LOSING RANDOM BITS
IN FULL WORD. AFTER MANY MAN HOURS IT WAS
FOUND THAT THE CMAB ~~33~~ CARD "6102R" (1104)
WHICH CONTAINED BIT 31 WAS ON T+V FOR
31 U). THIS IS BAD. NEW CARD WAS CURE
OF 'DOUBLE SELECTION' AND CORE "1" THEN
WORKED →

CORE "0" Bug 1000 4-4-67

IN RUNNING DIAGNOSTICS FOR CORE "1"

IT WAS NOTED THAT BIT 25 IN CORE "0"
WAS LOSING BAD SO SA'S WERE SWAPPED
WITH 24 1H8 1H7



+ INHIB. DRIVERS IN 2K11 2K12



IT DIDN'T WORK AS PHIL SAID THAT
BIT 25 WAS BAD THIS MORNING
AND DID SAME THING* SO
WE ARE BACK WHERE WE STARTED

Randy

* SEE PHIL'S NOTE

← PAGE

4-5-67 1:15

CORE "0" DIED IN THE TIMING CHAIN
TWICE BUT WOULDN'T REAPPEAR WHEN I POKED
AT IT
PULSES LOOKED GOOD?

Randy

P.S. IT LOOKED LIKE T2 DIDN'T HAPPEN

4-5-67 16:00

MORE ON CORE:

I INTERCHANGED ⁴1068 IN CORE 0 & 1
AND RAN HIGH SPEED CHECKER BOARD IN
CORE "0" NO BUGS ON MARGINS UNTILL
I CHANGED PATTERN, 11 "1" IS WORST CASE FOR
CORE "1" 11 "0" IS WORST FOR CORE "0"
I.E. 10 - 17 10'S IN CORE 0

THE Bug THAT I FOUND WAS:

BIT 24 WOULD GO AWAY UNDER CERTAIN
CONDITIONS OF BIT PATTERNS

I LOOK AT THE SA IN IH7 IN CORE
"0" AND ITS OUTPUT REFLECTED THE DIAGNOSTIC'S
REPLY
CALLED DEC AND GOT LAST SA IN STOCK
SEEM'S OKAY NOW.

MORE:

Beware when MARGINS ON IF + IH + IO B ARE
USED, THAT LINE IS ALSO CONNECTED TO PART
OF CORE CONTROL LOGIC TIMING CHAIN.
DON'T KNOW WHY BUT JUST THAT LINE

→

IT Explains why THE CHAIN DIED ON
SA'S MARGINS

THIS MORNING THE MARGINS ON CORE WERE:

0	1	2	3
+ 10	+10	+10	+10
- 7.5 to 8	-10	-10	-10

THIS AFTERNOON WITH CHECKER BOARD IN 1, RUNNING IN "0"

+ 9
- 7

AFTER ADJUSTING INHIB AND SLICE TO BAL
MARGINS, THEY WERE, UNDER ABOVE CIR. AS

FOLLOWS: + CHANGED SA IN 1A7
"0"
+ 11

- 10 OFF SCALE

CORE IS NOW BACK THE RIGHT
1664'S ARE NOW WAG BACK IN THE PROPER BOXES

2239 5 APR 67

INS TEST PART 2 COMPLAINED ASHC , 1

DIDN'T WORK.

~~LOOKER~~ INVESTIGATION SHOWED THAT

SETZM really didn't work if I's had just come from the location.

Bug was very timing sensitive.

Replaced bit 6 in AR

no change

seated MEM BUS TERMINATORS IN CORE 4

Bug went away

Ran TS MAIN for 2 in

Ran BLT for 4 min.

all OK

Only change is bit 6 which is too much work to change back, and terminators seated properly.

More O bug fixed this aft.

all of the last weeks troubles have had ~~change~~ relevant changes they all should be fixed.

GO PHIL!

ARR

1400 6 APR 66

TTY2 hangs up and won't
space after a carriage return -
sometimes.

MAGTAPE unit seems to
be missing ends of file and
possibly data in low slice level
line printer give spurious spaces

RRR

4-6-67

NOTES ON CORE MARGINS

How To TUNE CORE (R/W & INHIB CURRENTS)

LOAD HIGH SPEED CHECKER BOARD 677A

SA 100

D.S. ~~ALL~~ ALL BITS OFF EXCEPT 20, 21 TO SPECIFY CORE
BOX.

YOU HAVE OPTION ON NOISE PATTERNS, BITS 11 + 17

11(0)	17(0)	CORE	"0"
11(1)	17(0)	"	"1"
11(0)	17(1)	"	2
11(1)	17(1)	"	3

THESE ARE MOST CASE FOR OUR MODULES

PLEASE READ WRITE UP SO YOU WON'T
MUNG IT ALL UP

START PROG.

IF YOU READ FOLLOWING THE TTY BELL WILL
RING ON ERRORS. IF IT HALTED PUT BIT 1 OFF
IN D.S. AND CONTINUE —

NOW! INST. SP.

PUT RACK IF #1H +10A, +10B ON MARGINS
IN THE MODULES SELECTED AND SET MARGIN CONTROL
APPROPRIATELY

INST. CONTINUE

START DROPPING +10 TOWARD 0

IT SHOULD RUN ~~AT~~ AT LEAST TO 8.75V LOW BEFORE
BELLS SOUND

NOTE SINCE +10B ON THE TWO RACKS NAMED HAVE
SOME OF CORE CONTROL LOGIC IN THEM, IT WILL FAIL
IN ONE OF TWO WAYS

- ① BELL WILL RING FOR 15 SEC AND REPEAT EVERY 30 SEC.
~~SOME~~ THIS MEANS BITS COMING AND GOING.
- ② OR CORE WILL HANG



IF #1 HAPPENS BEFORE YOU GET TO 8V LOW
STOP PROG

PUT STOP ON ERROR ON PN PARITY BOX

LOOP → RESTART AT 100 WITH MARGINS BACK TO T10
ON MARGIN CONTROL AND START PROPPING
THEM AGAIN.

THIS TIME YOU SHOULD STOP ON THE ERROR WDR
WITH PMBR CONTAINING BAD WORD.

IT SHOULD BE ALL ONE'S OR ALL ZERO'S

NOTHING ELSE. ~~IF IT IS ALL SEEM~~ IF WORD IS

SO MESSED UP THAT YOU DON'T KNOW WHAT

IT SHOULD HAVE BEEN, EXAMINE LOC/2 FOR
IT CONTAINS AT THIS TIME THE PROPER WORD

IF ONLY A FEW BITS ARE BAD DO FOLLOWING:

IF UP TO 3 BITS WERE DROPPED FROM -1 WORD

CHECK SA'S FOR THOSE BITS INVOLVED

IF MORE THAN 3 • LOWER R/W CURRENT

NO MORE THAN $\frac{1}{4}$ TURN CCW ON BACK
BAY AT A TIME

TAKE CARE TO CLEAR ERROR ON PARITY BOX AND

TRY AGAIN FROM (LOOP) ONLY DEPRESS CONTINUE THIS

TIME. $\frac{1}{4}$ TURN LOWERS R/W CURRENT BY APPROXIMATELY 5 MA.

SO IF YOU HAVE TO LOWER BY MORE THAN $\frac{1}{2}$ TURNS

CHECK SA STRB TIMING

IMPORTANT

REMEMBER WHERE POT SETTING WAS SO YOU CAN RETURN TO IT IF YOU HAVE TO

IF UP TO 3 BITS WERE PICKED UP IN A LOC. CHECK INHIB DRIVER FOR BITS INVOLVED

IF MORE THAN 3 BITS, RAISE INHIB CURRENT

NO MORE THAN $\frac{1}{2}$ TURN CW ON BACK

BAY AT A TIME

CONTINUE ON AS NOTED

THE LIMIT ON INHIB CURRENT ADJUST IS ABOUT 4 TURNS. MONITOR VOLTAGE ON FRONT ~~OF~~ OF BAY

~~ON~~ DO NOT GO HIGHER THAN 60V.

TO RAISE HIGH MARGINS THE INVERSE IS TRUE ON ALL OF INFO GIVEN THUS FAR

SUMMARY:

Low MARGINS in BIT LOOSE MODE ↓ R/W CURRENT

" " " " PICK UP " ↑ INHIB " *

High MARGINS " " LOOSE MODE ↑ R/W CURRENT *

" " " " PICK UP " ↓ INHIB "

* LIMITS R/W 300 MA / INHIB 60V IF YOU MAKE IT MORE YOU BOUGHT THE CORE

NOW HOPEFULLY YOU HAVE ATLEAST A 18-20V SWING
ON MARGINS.

TO BALANCE ABOUT +10V ADJUST SA'S SLICE LEVEL
TO TUNE FOR MAX BAL.

IF #2 HAPPENS BEFORE YOU GET TO -8 OR +8
FORGET TUNING CORE UNTILL YOU GET CORE CONTROL LOGIC
TO WORK BETTER

SINCE R/W & INTIB CURRENT INTERACT ON BOTH
LOW + HIGH ENDS, WORK SLOWLY AND CAREFULLY
AND HAVE FUN

RANDY

P.S. SINCE PROG. RUNS IN CORE "0"
YOU HAVE TO MAKE ANOTHER CORE BOX, "0"
TO CHECK THE REAL CORE BOX "0"
CLEAR ISN'T IT.

46-67

CHANGED PRINTER LINE PULSE LAMP ASSY.

ALP,

SAT 8 APR 67

MAG TAPG DRIVE WENT LOAD. I FIXED SAME
WITH A SIGN STATING THAT THE DRIVE IS DOWN.

R

9 APR 67

TTY1 gives double characters

D. S. Smith

